

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well
2. NAME OF OPERATOR
Gene Milford
3. ADDRESS OF OPERATOR
P. O. Box 763, Hobbs, NM 88241
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 660' FEL of Sec. 33
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: | SUBSEQUENT REPORT OF: |
|--------------------------|-------------------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> |
| ABANDON* | <input checked="" type="checkbox"/> |
| (other) | |

5. LEASE
NM-0354427
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Packer Federal
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Cato San Andres
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 33, T8S, R30E
12. COUNTY OR PARISH
Chaves
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
4153 GL

(NOTE: Report results of multiple completion change on Form 9-331-C)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set cast iron bridge plug at 3450. Dumped 34' cement on bridge plug with dump bailer. Loaded hole with mud. Cut and pulled 5 1/2" casing from 2486. Ran Tubing and set 40 sack cement plug 2340 to 2550. Tagged top of plug at 2340. Set 40 sack cement plug 950 to 1090 across top of salt section. Set 50 sack cement plug from 244 to 356 across 8 5/8" casing shoe at 306. Tagged top of plug at 244. Spotted 15 sack plug at surface and installed dry hole marker. Well plugged for abandonment 9/26/84.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Peter W. Chester TITLE Agent DATE 10/3/84

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER

MAY 3 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

RECEIVED

MAY 8 1985

MAIL ROOM