STATE OF NEW MEXICO HERGY AND MINERALS DEPARTMENT

MO. OF COPIED ACCCIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
0.5.4.4.4.6.0	

O. _ CONSERVATION DIVISION

DISTRIBUTION P. O. BOX 2088	Form C-103
SANTA FE SANTA FE, NEW MEXICO 87501	Revised 10-1-78
FILE	5a. Indicate Type of Lense
LAND OFFICE	State X Fee
OPERATOR	5. State Oll & Gas Lease No.
	K 4649
CHADDA MOTICEL AND DEDODAL OF MELLIC	
SUNDRY NOTICES AND REPORTS ON WELLS GO NOT USE THIS FORM FOR PROPOSALS TO CHAILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERV	018.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL TO GAS TO DIAG C All and and a	7. Citt Adreement Name
well well other Plug & Abandoned	
Nume of Operator	8. Farm or Lease Name
STEVENS OPERATING CORPORATION	State "A"
Address of Operator	9. Well No.
P. O. Box 2408, Roswell, New Mexico 88201	1
i_ocation of Well	10. Field and Pool, or Wildcat
UNIT LETTER A 660 FEET FROM THE NORTH LINE AND 660	Cato San Andres
THE East LINE, SECTION 32 TOWNSHIP 8S RANGE 30E	
THE CINE, SECTION TOWNSHIP RANGE	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4137 GL 4148 KB	Chaves
Check Appropriate Box To Indicate Nature of Notice, Rep	port or Other Data
NOTICE OF INTENTION TO:	SSEQUENT REPORT OF:
PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORABILY ABANDON COMMENCE DRILLING OPHS	PLUG AND ABANDONMENT X
ULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT	
OTHER	
OTHER	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dat work) SEE RULE 1103.	es, including estimated date of starting any proposed
WORK) SEE ROLE 1103.	
5-10-83 Pulled rods (131 3/4") and tubing (108 joints 3400") out of hole. Ran cast iron
bridge plug & set @ 3350' and cement 35' above the CI	
350' free, 362' 50% free, 384' 10% free, 400' 0% stud	
35.0 11cc, 302 30% 11cc, 304 10% 11cc, 400 0% 3cdc	
5-11-83 Perforated 4 holes @ 340' and cemented w/150 sxs. Cla	200 11C11 + 2% CoC1 Comont
circulated to surface.	iss C + 2% Caci. Cement
circulated to surface.	•
5-12-83 Set dry hole marker.	
• .	
•	
·	
. I hereby certify that the information above is true and complete to the best of my knowledge and belief	
\mathcal{A}	
The Minney -	W 10 1000
rive Production Controll	er May 13, 1983
Orig. Signed by	1
Paul Kauts	y lan 84
Geologist TITLE	DATE Y COM DE

MAY 16 1983 HOBES OFFICE

, 1 J. 5