

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

NM3000 - ARIZONA

NM3000 - ARIZONA

NM3000 - ARIZONA

SUMMARY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., OR BLK. AND
SURVEY OR AREA

12. COUNTY OR PARISH

13. STATE

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐ Perf. and acidizeREPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-29-67 Lane wells ran correlation log 3451-2600'. Perforated 4 1/2" casing with one jet shot at each interval 3342, 44, 46, 50, 53, 55, 61, 63, 70, 3410, 12, 15, 30, 33 & 44 (15 holes) by Lane wells densilog measurements using 3 1/2" cased select fire gun, 11 gram NCF-II, FA charge, 0.35" diam. hole. Ran 110 jets. 2 3/8" tubing with Guib. KVL-30 pkr. tubing seated at 3456 and pkr swinging. 12-30-67 Chemical Engrs. spotted 4 bbls. 28% NE HCL acid across perfs. 3342-3444 and wash in 1/2 bbl. stages for 2 hours. Raised tubing and acidized perfs. 3342-3444 w/total 8000 gals. 28% NE HCL acid and 18 - 7/8" ball sealers. Flushed with 4000 gals. treated fresh water. Good ball action, balled out with 18 balls on formation. Swabbing.

18. I hereby certify that the foregoing is true and correct

SIGNED J. E. WilsonTITLE Area SuperintendentDATE 1-3-68

(This space for Federal or State office use)

APPROVED BY W. E. Wilson

CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

JAN 4 1968

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

District Engineer

U.S. GEOLOGICAL SURVEY
DALLAS, TEXAS

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.