

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

P. O. BOX 1980

HOBBS, NEW MEXICO 88240

5-85240

NM-0346362

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR  
Quanico Oil & Gas, Inc.
3. ADDRESS OF OPERATOR  
P. O. Box 755, Hobbs, NM 88241
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 660' FNL & 660' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO:                      | SUBSEQUENT REPORT OF:    |
|-----------------------------------------------|--------------------------|
| TEST WATER SHUT-OFF <input type="checkbox"/>  | <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/>       | <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/>     | <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/>          | <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE <input type="checkbox"/>    | <input type="checkbox"/> |
| CHANGE ZONES <input type="checkbox"/>         | <input type="checkbox"/> |
| ABANDON* <input checked="" type="checkbox"/>  | <input type="checkbox"/> |
| (other) <input type="checkbox"/>              | <input type="checkbox"/> |

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Woodman Federal

9. WELL NO.  
6

10. FIELD OR WILDCAT NAME  
Cato San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 28, T8S, R30E

12. COUNTY OR PARISH Chaves 13. STATE NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
4126 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Pump test well from July 27, 1985 thru August 13, 1985. Pump 100% water. It is proposed to plug & abandon as follows:

Set cast iron bridge plug at 3300' & cap with 5 sacks cement.  
Cut & pull 4 1/2" casing from 2000'  
Spot 100' plug across 4 1/2" casing stub from 1950' to 2050'  
Tag top of plug  
Spot 100' plug across 8 5/8" casing shoe from 284' to 384'  
Tag top of plug  
Set 50' surface plug with regulation marker  
Mud between all plugs  
Location to be cleaned and levelled


Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Donna Walker TITLE Agent DATE 8/21/85

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:



\*See Instructions on Reverse Side