

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

NMOCC - ARTESIA

NMOCC - HOBBS

BLM - SANTA FE

SUMMARY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. NM 0346362
2. NAME OF OPERATOR Sun Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 2792, Odessa, Texas 79760		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' from North line and 1980' from West line of Sec. 28, T8S, R30E		8. FARM OR LEASE NAME Woodman-Federal
14. PERMIT NO.		9. WELL NO. 7
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4134' Gr.		10. FIELD AND POOL, OR WILDCAT Cato-San Andres Ext.
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T8S, R30E
		12. COUNTY OR PARISH Chaves
		13. STATE New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Perf. and Acidizing ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-26-67 Lane Wells ran Gamma Ray Corr. log 3534-2600. Lane Wells perforated 4 1/2" casing with one jet shot at each interval 3402, 05, 10, 14, 16, 18, 25, 27, 31, 38, 40, 79, 84, 94, 96 and 3506 by Lane Wells densilog using 3 1/2" cased select fire gun, 11 gm, MFC2, RA charge, 0.375" hole. Ran 2 3/8" tubing seated @ 3513 and packer swinging. Chemical Engrs. spotted 4 bbls. 28% NE HCL acid across perfs. 3402-3506 and washed for 2 hours. Raised tubing and set packer with tubing seat at 3355. Acidized perfs. 3402-3506 with total 8000 gals. 28% NEHCL acid and 16 - 7/8" RCN ball sealers. Flushed with 4000 gals. treated fresh water. Good ball action, balled out w/16 balls on formation. Swabbing.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. E. Edison

TITLE

Area Superintendent

DATE 1-3-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

ACCEPTED FOR RECORD

District Engineer

*See Instructions on Reverse Side

JAN 14 1968

S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.