

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instruction
verse side)TE*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0155494 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Winkler Federal

9. WELL NO.

14

10. FIELD AND POOL, OR WILDCAT

Cato - San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

29-T8S-R30E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

NM0000 - 111111
NM0000 - 111111
BLM - SANTA FE

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole - Temporarily Abandoned.2. NAME OF OPERATOR
Sinclair Oil & Gas Company3. ADDRESS OF OPERATOR
P. O. Box 1920, Hobbs, New Mexico 882404. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' fr the South line and West lines.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4102' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Squeeze cement, perfs. & test X

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Total Depth Drilled 4000', PBTD 3492'. Well presently shut-in and temporarily abandoned in San Andres formation 3289-3358'.

PROPOSE TO: Squeeze cement San Andres perfs. 3289-3358', drill cut retainer and excess cement to 3960' and test. Perforate w/ 2- 3/8" jet shots at approx. 3836, 3840, 3842, 3844, 3847, 3849, 3851, 3879, 3881, 3884, 3919, 3923, & 3926', Holt Sand. Run packer to approx. 3770' and acidize w/approx. 5000 gals. w/approx. 2500 gals. fresh water overflush.

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Superintendent

DATE 7-15-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

Orig&4cc: USGS, Roswell, N. M.

cc: Regional Office

cc: file

TITLE

DATE

APPROVED

JUL 16 1968

J. W. SUTHERLAND
DISTRICT ENGINEER

*See Instructions on Reverse Side