

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Western States Producing Company	8. Farm or Lease Name Arco-State
3. Address of Operator 900 Building of the Southwest Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>north</u> LINE AND <u>1980</u> FEET FROM THE <u>east</u> LINE, SECTION <u>4</u> TOWNSHIP <u>8-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat Chaveroo
15. Elevation (Show whether DF, RT, GR, etc.) 4416' GL	12. County Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set 25 sack cement plug from 4238' back to 3970' in 4 1/2" casing.
- Cut off 4 1/2" casing at 2500'.
- Set 25 sack cement plug at 2000'.
- Set 50 sack cement plug from 381' back to 261'.
- Set 10 sack cement plug at surface.
- Removed head and welded on plate.
- Cleaned location and set marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don C. Bennett TITLE Operations Manager DATE 4/29/72

APPROVED BY John W. Runyan TITLE Geologist DATE FEB 22 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 6 1972

OIL CONSERVATION COMM.
HOBBS, N. M.