

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-020975-D

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

WHITE "B" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

9-10-31 NMPM

12. COUNTY OR PARISH

CHAUVES

13. STATE
N.M.

NM000 - ARTESIA

NM000 - HOBBS

BLM - 3

SUNDY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ DRILLING

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

330' FNxE LINES Sec. 8 (Unit A, NW1/4 NE1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

4265.5 RDB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

On 2-1-68, 4 1/2" O.D. 9.5" J-55 casing was set @ 4673' w/100 #4
Incor. + 4% gel + 400 #4 mesh. Tested casing w/2150
psi for 30 minutes. Seat O.K.

Perforated intervals 4516-22, 41-43, 74-78, 95-97, 4642-50' w/2150 psi.
Acidized w/5000 gal 20% Swat 6 BWPN. No show of oil.

= Set CIBP 4472 - 593 w/100 #5x. Cement =
LEFT 5' CMT ON CIBP @ 4472.

Perforated 4360-68 w/2150 psi. Acid 500 gal 28% Swat 5 BWPN. TR. Oil.
= Set CIBP 4299 - 593 w/100 #5x. Cement =

Perforated 3923, 3932-3938-42, 55-57, 61-64, 76-80 w/2150 psi.
Acidized w/4000 gal 28%.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

2-27-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

District Engineer

RECEIVED

FEB 28 1968

U. S. GEOLOGICAL SURVEY
BOSWELL, NEW MEXICO

044- USGS-Ros

1- NSW

1- SUSP

1- RRY