

N MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

WELL ☐

GAS WELL ☐

OTHER- SWD

Name of Operator:

Shell Oil Company

3. Address of Operator:

P.O. Box 1509, Midland, Texas 79702

4. Location of Well:

UNIT LETTER H, 1980 FEET FROM THE North LINE AND 660 FEET FROM  
THE East LINE, SECTION 17 TOWNSHIP 9S RANGE 30E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Thelma Crosby F

9. Well No.

1

10. Field and Pool, or Wildcat

Cato (San Andres)

15. Elevation (Show whether DF, RT, GR, etc.)

4035' DF

12. County

Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull prod equipment.
2. Spot 25 sx cmt @ TD (est. 300' of fill for 20 sx cmt). Woc to set then tag.
3. Fill the hole w/salt gel mud consisting of 10# brine w/25# of gel/bbl.
4. Cut 4 1/2" csg from as deep as possible.
5. Spot 200 sx cmt @ stub before pulling out csg (est. 240' of fill for 200 sx cmt in 14" hole). Allow cmt to set then tag.
6. Spot 100 sx cmt above top of salt @ 940' (est 200' of fill for 100 sx cmt in 11" hole). Allow cmt to set then tag.
7. Spot 50 sx cmt from 320' upward. Top of cmt must be 50' up inside 8 5/8" csg (est. 80' of fill inside 8 5/8" csg). Allow cmt to set then tag.
8. Spot cmt in 8 5/8" @ surf from btm of cellar down 20'. Allow to set.
9. Mark location w/4" OD steel pipe @ least 4' above GL w/"Thelma Crosby F No. 1, Section 17-9S-30E" welded on pipe. Show distance to lease lines.
10. Clean location.

Note: All cmt must be introduced down tubing.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

*W.R. Greene*

TITLE

W.R. Greene

Staff Prod. Eng.

8-1-79

APPROVED BY

Orig. Signed by  
Jerry Sexton

TITLE

Dist. 1, Supv.

CONDITIONS OF APPROVAL, IF ANY

AUG 3 1979