

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

**JUL - 6 1978**

**O. C. C.**  
**ARTESIA, OFFICE**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-55

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>K-2019</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>Champlin State</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>Chaveroo</b>
12. County <b>Chaves</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	2. Name of Operator <b>Hytech Energy Corporation</b>
3. Address of Operator <b>400 Wilco Bldg. - Midland, Texas 79701</b>	4. Location of Well UNIT LETTER <b>B</b> <b>660'</b> FEET FROM THE <b>North</b> LINE AND <b>1980'</b> FEET FROM THE <b>East</b> LINE, SECTION <b>4</b> TOWNSHIP <b>8-5</b> RANGE <b>33-E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4426 GR</b>	16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set cast iron bridge on wireline at 4200' and spot 20' of cement with dump bailer.
2. Free point 4 1/2" csg. and cut off at approximately 2000'.
3. Spot 40 sack plug from 2050 to 1950 (100' Plug)
4. Spot 40 sack plug from 380 to 280' (100' Plug)
5. Spot 10 sack plug at surface, cut off head, weld on plate and clean location.

THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE BEGINNING OF  
PLUGGING OPERATIONS FOR THE C-103  
TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Jerry Sexton* TITLE Division Operations Mgr. DATE 6-30-78

Orig. Signed by  
**Jerry Sexton**  
Dist. 1. Supv.

TITLE

DATE

**JUL 10 1978**