

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1421.
5. LEASE DESIGNATION AND SERIAL NO.

NMCCC - ARTESIA

NMCCC - HOBBS

BLM - SANTA FE

DRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

NM 027395

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Pennzoil United, Inc.

3. ADDRESS OF OPERATOR

P. O. Drawer 1828 - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

810 FSL & 1980 FEL of Sec. 33, T-8-S, R-31-E,
Chaves County, New Mexico

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Pubco "33" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 33, T-8-S, R-31-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4258 GL

12. COUNTY OR PARISH

Chaves

13. STATE

N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-22-68 Ran Correlation log, perforate 3 holes in same place @ 10,586'. Ran 2 3/8" tbg. and packer - Displace hole w/crude oil and treat perforations w/500 gals mud acid. Swab and recover flush oil then swab 100% water. Prepare to squeeze perfs @ 10,586'.

RECEIVED
OCT 3 1968
U. S. GEOLOGICAL SURVEY
DOWNEY, NEW MEXICO

18. I certify that the foregoing is true and correct

SIGNED

Redney C Boyd

TITLE

Petroleum Engineer

DATE

10-4-68

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

J. W. Little
District Engineer

*See Instructions on Reverse Side