

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-5364	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Rapid Company, Inc.		8. Farm or Lease Name State "C"
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88240		9. Well No. 2
4. Location of Well UNIT LETTER P 990 FEET FROM THE South LINE AND 990 FEET FROM East THE 34 LINE, SECTION 14 E TOWNSHIP 31 E RANGE NMPM.		10. Field and Pool, or Wildcat Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4416 DF		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged & abandoned as follows:

**Set Cast Iron Bridge Plug at 3000'.
Capped with 35' cement (5 sacks)
Cut and pulled 5 1/2" casing from 1280'
Went in hole with 2" tubing
Loaded hole with mud (15 sacks)
Set 30 sack cement plug from 1330' to 1230'
Set 40 sack cement plug from 375' to 275'
Set 10 sack cement plug from 20' to 0'.
Installed regulation 4 1/2" dry hole marker
Cleaned and leveled location.**

Work complete 7/14/75.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Harold Hakes* TITLE Agent DATE 2/7/79

APPROVED BY *Nathan E. Vegg* TITLE OIL & GAS INSPECTOR DATE FEB 14 1979

CONDITIONS OF APPROVAL, IF ANY:

ON COMMISSION COMM.
H. M.