

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K 745	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
H. L. Brown, Jr.		Sunray State
3. Address of Operator		9. Well No.
P. O. Box 2237, Midland, Texas 79702		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER E 660 FEET FROM THE W LINE AND 1980 FEET FROM THE N LINE, SECTION 16 TOWNSHIP 8S RANGE 31E NMPM.		Siete San Andres
11. Elevation (Show whether DF, RT, GR, etc.)		12. County
4220 GR		Chavez

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMOCC notified 24 hours prior to plugging operations by Pool Well Service and a NMOCC representative was on location to witness plugging operations.

6-28-88 - Prep to commence plugging and abandonment operations. NMOCC witness on location. Rigged up Pool Well Service. Pulled and laid down rods. Nipped up blow out preventor. Pulled tubing out of hole. Ran in hole with 4 1/2" CIPB on tubing and set at 3675'.

6-29-88 - Spotted 35' of cement (plug #1) on top of CIBP. No other progress made due to mechanical problems. Plug #1 was not placed due to pump problems.

6-30-88 - Resumed plugging operations. Spotted 5 sx cement (plug #2) from 3675'-3622'. Circulated hole with 10# mud. Set 25 sx cement (plug #3) from 3055'-2694'. Tripped out of hole with tubing. Welded on pull nipple, found free point of 4 1/2" casing at 590'. Received permission from Jerry Sexton w/ NMOCC to leave 4 1/2" casing in hole. Perforated at 366'. Tagged in hole with 1 joint of tubing. Pumped 80 sx cement (plug #4), displaced to 200'.

7-01-88 - Tagged in hole and tagged plug #4 at 179'. Cut-off wellhead. Dumped 10 sx cement (plug #5) at surface. Welded on plate and dry hole marker. P & A Complete.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jack Griffin TITLE Production Engineer DATE 10-21-88

OIL & GAS

JAN 2