## OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO 88240

May 1, 1969

Mr. H. L. Brown, Jr. 309 Midland Tower Midland, Texas 79701

Dear Mr. Brown:

On April 24 we returned Form C-103 covering work done on your Sunray State Well No. 1 located in Unit E of Section 16, T-8-S, R-31-E. On that form you indicated that cement did not circulate on the 8 5/8" casing and we requested that you run 1" in the annular space and circulate cement. On April 29 we received another Form C-103 showing that the cement had circulated on this casing string.

Since there is a question on whether or not the cement did actually circulate on this well, please have the cementing company submit an affidavit stating that cement did indeed circulate on this well. When this affidavit has been received by this office, we will proceed with the issuance of an allowable.

Yours very truly,

OIL CONSERVATION COMMISSION

Joe D. Ramey Supervisor, District 1

JDR/mc

## OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO 88240

100 - 100 - 100 - 100 - 100 100011 - 000 000 - 100 100011 - 1000 - 1000 00

Beach and Beorger

 $\{ (x_i) \in X_i \}$ 

1

7 n. N

-----

S sen fintenses den 100 in Marten of politic and 10 f a fulle entre rivern for total, stadde bereit og ser in stepent skadt an officielt all 100 in 100 october 10 october officielte officielt allen fills series for total officielt by left deriver, and and arth the total of the october 10 october stepe

I I I MEY MINY

U.S. CONSERVE 10% IN ADVISION

an Buildsen Saparkinna do Mira