

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- Plug and abandon

Name of Operator

Harvey E. Yates Company

Address of Operator

P. O. Box 1933, Roswell, N. M. 88201

Location of Well

UNIT LETTER D 990 FEET FROM THE North LINE AND 660 FEET FROM

THE West LINE, SECTION 34 TOWNSHIP 7S RANGE 30E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

4100' KB

7. Unit Agreement Name

8. Farm or Lease Name

Heyco Crosby J

9. Well No.

1

10. Field and Pool, or Wildcat

Wildcat

12. County

Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
ULL OR ALTER CASING ☐
OTHER ☐
PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-11-79 Plugged in the following manner:
Plug #1 - 100' plug from 750' - 850'
Plug #2 - 100' plug from 240' - 340'
10 Sx Surface plug with dry hole marker set on top.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNED Paul J. Harder TITLE Engineer DATE 7-12-79
PROVED BY Alta Newton TITLE OIL & GAS INSPECTOR DATE 7-12-1981
CONDITIONS OF APPROVAL, IF ANY: