

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator <b>The Fundamental Oil Corporation</b>		8. Farm or Lease Name <b>Superior-Price</b>	
3. Address of Operator <b>1000 V &amp; J Tower, Midland, Texas 79701</b>		9. Well No. <b>1</b>	
4. Location of Well UNIT LETTER <b>D</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>24</b> TOWNSHIP <b>8-S</b> RANGE <b>33-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat</b>	
15. Elevation (Show whether DF, RT, GR, etc.) <b>4339 G.L.</b>		12. County <b>Chaves</b>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 9225'. Spot 25 sx cement plug from 9225 to 9145, 25 sx. cement plug from 3768' to 3688'. Cut 8 5/8" casing at 1350'. Spot 25 sx. cement plug from 1350' to 1297' (salt section is from 2010' to 2500'). Spot 25 sx cement plug from 420' to 367' and 10 sx. in top of surface casing and install marker. Plugging operations complete November 4, 1969.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *O. D. Butler* O. D. Butler TITLE Agent DATE 11-6-69  
APPROVED BY *John W. Runyan* TITLE Geologist DATE MAR 4 1970  
CONDITIONS OF APPROVAL, IF ANY: