

**UNITED STATES**  
**DEPARTMENT OF THE INTERIOR**  
**GEOLOGICAL SURVEY**

SUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0109856

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

BAM Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21-T14S-R30E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. NAME OF OPERATOR

McClellan Oil Corporation

3. ADDRESS OF OPERATOR

Post Office Box 848, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface

660' FS & WL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3857' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Pursuant to verbal instructions February 21, 1977, this test was plugged and abandoned as follows:

In attempting to pull the 4 1/2" casing it was determined that this casing was sufficiently cemented that none could be recovered. Therefore, a cement plug was placed from 2112-2000', 1230'1130' (Base of Salt), and a 30' plug at surface, with cement in the annulus between the 8-5/8" and 4 1/2" casing from the surface. A dry hole marker will be erected and the location cleaned and surface restored pursuant to BLM stipulations. You will be notified when the location is ready for inspection. Heavy mud was placed between all plugs.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Joe J. Mc Clellan*

TITLE

Owner

DATE

2/22/77

(This space for Federal or State office use)

APPROVED BY

*Joe J. Lam*

TITLE

ACTING DISTRICT ENGINEER

DATE

FEB 10 1978

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 13 1978

O. C. C.  
AMERICA, OFFICE

14-00000  
FEB 14 1978  
WINSTON-SALEM, N.C.  
MAY 14 1978