

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

LEASE DESIGNATION AND SERIAL NO.

88240 NM 0343765 A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER Shut in gas well

2. NAME OF OPERATOR
C & C OPERATING CORPORATION

3. ADDRESS OF OPERATOR
2211 RIDGEWAY, ARDMORE, OKLAHOMA 73401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 1980' FSL & 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, ET, GR, etc.)
3886'

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
W.R. MEANS

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
VEST RANCH QUEEN

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
S 28, T 14 S, R 30 E

12. COUNTY OR PARISH
CHAVES

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETION	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set CIBP @ 2075 ' with 35' cmt.
2. Cut and pull 3 1/2" and set 100' CP on top of stub
3. Set CP 1275'-1375'.
4. Set CP 497-397' & tag.
5. 15 Sxs @ surface & D.H.M.

Place mud between plugs.
Work should commence in September, 1985.

MORRIS K. CHAMBLESS

18. I hereby certify that the foregoing is true and correct

SIGNED

VICE PRESIDENT

DATE 7-31-1985

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
DATE
PETER W. CHESTER

AUG 9 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side