

Form 1000  
(November 1984)  
(Formerly 9-101)

UNITED STATES N. M. OIL CONS. COMMISSION  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
HOBBS, NEW MEXICO 88240

Department of the Interior  
Bureau of Land Management  
Expires August 31, 1985

LEASE DESIGNATION AND SERIAL NO.

NM-0338-A

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

PO Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

Unit Letter A, 660' FNL & 990' FEL

14. PERMIT NO

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3999' DF

12. COUNTY OR PARISH

Chaves

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

Other: Squeeze Wtr & Perforate

NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) MIRU 3/7/83. Install BOP. TOH with tubing and packer.
- 2) Set cement retainer at 9995'. Squeeze perfs 10,024'-038' with 30 sx. Class "H" cement. Reverse out 45 sx.
- 3) Spot 200 gallons 10% acetic acid 9900'-9700'.
- 4) TIH with packer. Circulate backside with inhibited 2% KCL. Set packer at 9785'. ND BOP. NU tree.
- 5) Perf 5 1/2" casing with 1 11/16" gun 9833'-94' with 2 jsp (12', 24 holes).
- 6) Acidize perfs 9883'-94' with 1000 gallons 7 1/2% Moroflow acid and 25,000 scf N<sub>2</sub>.
- 7) Swab back load.
- 8) Shut-in well. Workover unsuccessful.

\*\*NAME CHANGE-From Peery Federal No. 4 to E. L. Peery Federal Com. No. 1

18. I hereby certify that the foregoing is true and correct

397-3571

SIGNED

TITLE Hobbs Area Superintendent, DATE 3/22/88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD  
PETER W. CHESTER  
DATE

APR 15 1988

BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA

\*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.