## N. M. U. C. M. LUEL

•

	RTMENT OF THE	ES SI INTERIOR VE	ther instructions _n rse side)	re- 5. LEAS	Budget Bureau No	
DEIA	GEOLOGICAL SU				NM-0338-A	
				6. IF I	NDIAN, ALLOTTEE OR	TRIBE NAY
	NOTICES AND REP proposals to drill or to deep					
Use "AP	proposals to drill or to deep PPLICATION FOR PERMIT—	" for such proppals	CEIVEI	D_	· .	•
				7. UNI	AGRBEMENT NAME	•
WELL X WELL OTH	HÊR .		11-2-1070-		M OR LEASE NAME	
2. NAME OF OPERATOR JUL 31 1970				1	Peery Federal	
TEXACO Inc.				9. WEL		
ADDRESS OF OPERATOR	Hobbe New Morris	0 88200	O. C. C.		4	- ·
P.O. Box 728, Hobbs, New Mexico 88240 ARTEBIA, EFFICE 4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					LD AND POOL, OR WI	LDCAT
See also space 17 below.) At surface space is the space of the space o				Und	Undesignated	
660' FNL and 900' FEL, Sec. 29, T-15-S, R-30-E					11. SEC., T., R., M., OR BLK. AND SURVET OR ARDA	
		,			29, T-15-S,	R-30-
14. PERMIT NO.		w whether DF, RT, GR, G	etc.)		UNTY OR PARISH 13.	. STATE New Me
Regular	3999'	(DF)		Ch	aves	
16. Chec	k Appropriate Box To	Indicate Nature	f Notice Report	or Other D	ata	· .
				SEQUENT REP		
NOTICE OF	INTENTION TO:	r1			4	
TEST WATER SHUT-OFF	PULL OR ALTER CASING		VATER SHUT-OFF	<u>~</u>	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	·	BACTURE TREATMENT		ALTERING CASING	-
SHOOT OR ACIDIZE	ABANDON*		Other)	L		
REPAIR WELL	CHANGE PLANS		(Nore Report rel	sults of mult	port and Log form.)	¥ell
(Other) 17. DESCRIBE PROPOSED OR COMPLET	TED OPERATIONS (Clearly state directionally drilled, give sub	all pertinent details	and give postinent d	ates includin	a estimated date of	starting
	11-3/4" OD		s. casing set		•**	· · · ·
Ran 4986' (152 joi TLW w/4% gel and 5	11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk.	42# H-40 Sml # casing and Followed w/2	s. casing set cemented at 00 sx Class C	5000' w/	'900 sx	· ·
Ran 4986' (152 joi TLW w/4% gel and 5 Plug at 4966'. Jo	11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk.	42# H-40 Sml # casing and Followed w/2	s. casing set cemented at 00 sx Class C	5000' w/	'900 sx	· · · ·
TLW w/4% gel and 5 Plug at 4966'. Jo	11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0	42# H-40 Sml P# casing and Followed w/2 00 PM July 23	s. casing set cemented at 00 sx Class C , 1970.	5000' w/ w/10# s	900 sx alt/sk.	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c	<pre>11-3/4" OD ints) 8-5/8" OD 32 # gilsonite/sk. b complete at 3:0 casing w/1500# for prilled out of </pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1	5000' w/ w/10# s to 9:40 500# for	(900 sx alt/sk. AM July 5 30	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c	<pre>11-3/4" OD ints) 8-5/8" OD 32 # gilsonite/sk. b complete at 3:0 casing w/1500# for prilled out of </pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1	5000' w/ w/10# s to 9:40 500# for	Y900 sx salt/sk. AM July s 30	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1	5000' w/ w/10# s to 9:40 500# for	Y900 sx salt/sk. AM July s 30	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1	5000' w/ w/10# s to 9:40 500# for	Y900 sx salt/sk. AM July s 30	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 70. Tested OK	5000' w/ w/10# s to 9:40 500# for . Job (	Y900 sx salt/sk. AM July c 30 complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 70. Tested OK	5000' w/ w/10# s to 9:40 500# for . Job (	Y900 sx salt/sk. AM July c 30 complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 70. Tested OK	5000' w/ w/10# s to 9:40 500# for . Job (	Y900 sx salt/sk. AM July c 30 complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C 1970. from 9:10 AM Retested w/1 0. Tested OK	5000' w/ w/10# s to 9:40 500# for . Job o	AM July and July 30 complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C 1970. from 9:10 AM Retested w/1 0. Tested OK	5000' w/ w/10# s to 9:40 500# for . Job o	AM July and July 30 complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C 1970. from 9:10 AM Retested w/1 0. Tested OK	5000' w/ w/10# s to 9:40 500# for . Job o	AM July and July 30 complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C 1970. from 9:10 AM Retested w/1 0. Tested OK	5000' w/ w/10# s to 9:40 500# for . Job o	AM July and July 30 complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM,</pre>	42# H-40 Sml # casing and Followed w/2 00 PM July 23 5 30 minutes	s. casing set cemented at 00 sx Class C 1970. from 9:10 AM Retested w/1 0. Tested OK	5000' w/ w/10# s to 9:40 500# for . Job o	AM July and July 30 complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested O minutes from 11:00 11:30 AM, July 24,	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. ob complete at 3:0 casing w/1500# for OK. Drilled out of O AM to 11:30 AM, 1970.</pre>	42# H-40 Sml Followed w/2 00 PM July 23 or 30 minutes cement plug. July 24, 197	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 0. Tested OK	5000' w/ w/10# s to 9:40 500# for . Job (	AM July and July 30 complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM, 1970. going is true and correct</pre>	42# H-40 Sml P# casing and Followed w/2 00 PM July 23 5 30 minutes cement plug. July 24, 197 Assistan	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 0. Tested OK 4	5000' w/ w/10# s to 9:40 500# for . Job o	AM July alt/sk. AM July complete	
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested O minutes from 11:00 11:30 AM, July 24,	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out co AM to 11:30 AM, 1970. going is true and correct</pre>	42# H-40 Sml Followed w/2 00 PM July 23 or 30 minutes cement plug. July 24, 197	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 0. Tested OK 4	5000' w/ w/10# s to 9:40 500# for . Job o . Job o . Job o . Job o	AM July and July 30 complete	, 1970
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00 11:30 AM, July 24,	<pre>11-3/4" OD ants) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out of OAM to 11:30 AM, 1970. </pre>	42# H-40 Sml P# casing and Followed w/2 00 PM July 23 5 30 minutes cement plug. July 24, 197 Assistan	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 0. Tested OK 4	5000' w/ w/10# s to 9:40 500# for . Job o . Job o . Job o . Job o	AM July and July and complete	<b>, 1</b> 970
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00 11:30 AM, July 24,	<pre>11-3/4" OD ants) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out of OAM to 11:30 AM, 1970. </pre>	42# H-40 Sml P# casing and Followed w/2 00 PM July 23 c 30 minutes cement plug. July 24, 197 Assistan TITLE Superin	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 0. Tested OK 4	5000' w/ w/10# s to 9:40 500# for . Job of . Job of	AM July alt/sk. AM July complete	<u>, 1970</u>
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00 11:30 AM, July 24,	<pre>11-3/4" OD ants) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out of OAM to 11:30 AM, 1970. </pre>	42# H-40 Sml P# casing and Followed w/2 00 PM July 23 5 30 minutes cement plug. July 24, 197 Assistan	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 0. Tested OK 4	5000' w/ w/10# s to 9:40 500# for . Job of . Job of	AM July and July and complete	<b>, 1</b> 970
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00 11:30 AM, July 24, 18. I hereby certify fat the fore SIGNED (This prace for Federal or St APPROVED BY CONDITIONS OF APPENDEN	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out of AM to 11:30 AM, 1970.  going is true and correct  fate office use)  fate office use)  fate office use) </pre>	42# H-40 Sml P# casing and Followed w/2 00 PM July 23 c 30 minutes cement plug. July 24, 197 Assistan TITLE Superin	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 0. Tested OK 4	5000' w/ w/10# s to 9:40 500# for . Job of . Job of	AM July alt/sk. AM July complete	<b>, 1</b> 970
TLW w/4% gel and 5 Plug at 4966'. Jo Tested 8-5/8" OD c 24, 1970. Tested 0 minutes from 11:00 11:30 AM, July 24,	<pre>11-3/4" OD nts) 8-5/8" OD 32 # gilsonite/sk. bb complete at 3:0 casing w/1500# for OK. Drilled out of AM to 11:30 AM, 1970.  going is true and correct  fate office use)  fate office use)  fate office use) </pre>	42# H-40 Sml P# casing and Followed w/2 00 PM July 23 c 30 minutes cement plug. July 24, 197 Assistan TITLE Superin	s. casing set cemented at 00 sx Class C , 1970. from 9:10 AM Retested w/1 0. Tested OK 4	5000' w/ w/10# s to 9:40 500# for . Job of . Job of	AM July alt/sk. AM July complete	<b>, 1970</b>