SHOOT OR ACIDIZE

REPAIR WELL

## UNITE STATES SUBMIT IN TRIPLICAT DEPARTMENT C. THE INTERIOR (Other instructions on verse side) Form approved. Budget Bureau No. 42-R1424. Form 9-331 (May 1963) 5. LEASE DESIGNATION AND SERIAL NO. GEOLOGICAL SURVEY NM-3286-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) ------7. UNIT AGREEMENT NAME GAS WELL WELL OTHER Dry NAME OF OPERATOR 8. FARM OR LEASE NAME Sauer Federal McGrath & Smith, Inc. 3. ADDRESS OF OPERATOR 9. WELL NO. 418 Bldg. of the Southwest, Midland, Texas LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT At surface Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 1980' FNL and 1980' FEL Sec. 23, T12S, R30E 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. GL 3986 N.M. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING FRACTURE TREAT

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*


SHOOTING OR ACIDIZING

(Other) \_

ABANDON\*

CHANGE PLANS

Spudded 8-6-70. Drld. 11" hole to 354'. Cmtd. 8 5/8-20% csg. at 353' with 175 sx. Circ. cmt. WOC 18 hrs. Tested 8 5/8 to 350 psi - OK. Drld. 7 7/8" hole to TD 2905'. Reached TD 8-10-70. Cored Queen 2282-2310. NS. Ran GR-Acoustilog, MLL, LL. Plan to P&A as follows: Spot cmt. plugs as follows: 35 sx. top Queen, 35 sx. base salt, 35 sx. 300-400', 10 sx. in top of 8 5/8" csg. Fill hole with mud between plugs. Install DHM.



ABANDONMENT\*

O T homely continue that the formula is to a series			
8. I hereby certify that the foregoing is true and correct	£		
signed Marcylory	TITLE	Sup't.	DATE 8-20-70
(This space for Federal or State office use)		DISTRICT ENGINEER	AUG 2 1 1970
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE 1100 ~ 1 1010

RECEIVED

AUG 25 1970

D. C. L.