

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-3259	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
Name of Operator MARTINDALE PETROLEUM CORPORATION		8. Farm or Lease Name SUN STATE
Address of Operator P.O. BOX 2403 HOBBS, NM 88240		9. Well No. 1
Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>7S</u> RANGE <u>30E</u> NMPM.		10. Field and Pool, or Wildcat CATO SAN ANDRES
11. Elevation (Show whether DF, RT, GR, etc.) 4205 GR		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CASING PARTED @ 1050'

Run 58 jts. 2 1/16" integral tbg and 1050' 2 3/8" tbg.

Circulate hole, mud up w/ mud-laden fluid.

Pump 25 sx cement plug @ approximately 300'.

Pump 20 sx cement plug in annulus between 8 5/8" and 4 1/2" csg.

Pull tbg and pump 20 sk cement plug in and out of stub @ 1050'.

Top plug set w/ 5 sx with regulation marker.

No casing will be pulled.

OCD will be notified 24 hours prior to plugging operations.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Secretary-Treasurer DATE 06/13/84

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT 1 SUPERVISOR

DATE JUN 14 1984

RECEIVED
JUN 13 1984
O.C.D.
HOBBS OFFICE