

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-13734

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ WELL GAS ☐ WELL OTHER ☐

2. NAME OF OPERATOR

The Wil-Mc Oil Corporation

3. ADDRESS OF OPERATOR

Drawer 1889, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

Unit B, 660' from North line, and 1980' from East
line, Section 9, Township 8 South, Range 33 East

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4416' Gr.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 9

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Chaveroo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 9-8S-33E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent
to this work.)*

1. Set cast iron bridge plug immediately above perforations (4252'-4296') with 35' cement on top of plug.
2. Obtain free point and shoot of 4 1/2" casing - pull casing.
3. Run tubing and displace hole with 25 lbs./bbl. mud to 4 1/2" pipe stub.
4. Spot 100' cement plug over pipe stub.
5. Displace hole with mud to salt section at approximate depth of 1400'.
6. Spot 100' cement plug over salt section.
7. Displace hole with mud to surface pipe shoe.
8. Spot 100' cement plug over surface pipe shoe.
9. Finish displacing hole with mud and cap with 10 sack cement plug.
10. Clean and level location

Estimate work will commence about 10-1-73, depending on availability
of casing puller.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jm Kulgetuck

TITLE

Engineer

DATE

9-18-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
SEP 26 1973
ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; and or other material placed below, between and above plugs; amount, size, method of parting of any casing; liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.