Orm 9-331 May 1963) UNITED STATES M. O. C. COPT DEPARTME OF THE INTERIOR (Other instructions on re- verse side)	Form approved. Budget Bureau No 5. LEASE DESIGNATION AND	
GEULUGICAL SURVEY	NM-054926-A	
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR :	TRIBE NAM
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	7. UNIT AGHREMENT NAME	
OIL GAS WELL OTHER		
_Read & Stevens, Inc.	8. FARM OR LEASE NAME Jackson	
B. ADDRESS OF OPERATOR	9. WELL NO.	
P. O. Box 2126, Roswell, New Mexico 88201 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. RIELD AND POOL, OR WILL Undesignated	DCAT
1980' FNL & 1980' FWL Sec. 25, Township 12 South, Range 30 East	11. SEC., T., R., M., OR BLK. A SURVEY OR AREA	· .
4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	Sec. 25, T-12-S <u>N.M.P.M.</u> 12. COUNTY OR PARISH 13.	
3992.2 GR - 4002.2 RKB	Chaves New	w Mexi
6. Check Appropriate Box To Indicate Nature of Notice, Report, or C		1
	UENT REPORT OF:	
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING REPAIR WELL CHANGE PLANS (Other)	ABANDONMENT*	
(Other) (Note: Report results Completion or Recomp 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, proposed work. If well is directionally doiled give pertinent details, and give pertinent dates,	of multiple completion on We letion Report and Log form.)	
1. Well was not directionally drilled.		
2. Plugged well in following manner:		
 Plugged well in following manner: Hole full of good mud. 10.2 wt., 38 Vis. 		
	(a) A set of the se	
Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'.	(a) A set of the se	
Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'. Set 35 sx. cement plug 1469'-1369'. Set 35 sx. cement plug 375'- 275'. 8 5/8" shoe @ 327'.	As the new contraction of the co	
<pre>Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'. Set 35 sx. cement plug 1469'-1369'. Set 35 sx. cement plug 375'- 275'. 8 5/8" shoe @ 327'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker.</pre> 3. Will notify when location is ready for inspection.		
 Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'. Set 35 sx. cement plug 1469'-1369'. Set 35 sx. cement plug 375'- 275'. 8 5/8" shoe @ 327'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker. 3. Will notify when location is ready for inspection. 	APR 1 11974 ARTISIA, MELANISA	
 Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'. Set 35 sx. cement plug 1469'-1369'. Set 35 sx. cement plug 375'- 275'. 8 5/8" shoe @ 327'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker. 3. Will notify when location is ready for inspection. 	APR 1 1974 ARTESIA NEW MEXICO	
 Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'. Set 35 sx. cement plug 1469'-1369'. Set 35 sx. cement plug 375'- 275'. 8 5/8" shoe @ 327'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker. 3. Will notify when location is ready for inspection. 	U.S GEOLOGICAL SURVEY	
<pre>Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'. Set 35 sx. cement plug 1469'-1369'. Set 35 sx. cement plug 375'- 275'. 8 5/8" shoe @ 327'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker. 3. Will notify when location is ready for inspection.</pre>	APR 1 1 1974 ARTESIA NEW MEXICO DATE 3/28/74	
 Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'. Set 35 sx. cement plug 1469'-1369'. Set 35 sx. cement plug 375'- 275'. 8 5/8" shoe @ 327'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker. 3. Will notify when location is ready for inspection. 8. I hereby certify that the foregoing is true and correct siGNED. TITLE Agent (This space for Federal-or State office use)	NEW MEXICO	
 Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'. Set 35 sx. cement plug 1469'-1369'. Set 35 sx. cement plug 375'- 275'. 8 5/8" shoe @ 327'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker. 3. Will notify when location is ready for inspection. 8. I hereby certify that the foregoing is true and correct SIGNED	NEW MEXICO	
Hole full of good mud. 10.2 wt., 38 Vis. Set 35 sx. cement plug 2406'-2306'. Set 35 sx. cement plug 1469'-1369'. Set 35 sx. cement plug 375'- 275'. 8 5/8" shoe @ 327'. Set 10 sx. cement plug 10'- 0'. Installed regulation marker. 3. Will notify when location is ready for inspection. 8. I bereby certify that the foregoing is true and correct SIGNED	DATE 3/28/74	

ACTING DIS





.