Form 9-331 (May 1963)

UNITED STATES UNITED STATES Drawerotter in triplicate on red DEPARTMENT OF THE INTERIOR sarse into 88210

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND RECEIVED

GEOLOGIC	CAL SURVEY	NM 0478452
SUNDRY NOTICES AN (Do not use this form for proposals to drill o Use "APPLICATION FOR P	D REPORTS ON WELLS r to deepen or plug back to a different reservoir. DERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME MAY - 3 199
oil GAS X other Plug an		7. UNIT AGREEMENT NAME . C. D. ARTESIA. OFFICE
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
Dalport Oil Corp.		Federal "X" b
3. ADDRESS OF OPERATOR		9. WELL NO.
3471 First National Bank	Bldg., Dallas, Tx 75202	
4 LOCATION OF WELL (Report location clearly and in	accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface		Vest Ranch-Qn. Assoc.
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
660' FN & EL		
		5-15S-30E
14. PERMIT NO. 15. ELEVAT	ions (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
		Chaves NM
16. Check Appropriate	Box To Indicate Nature of Notice, Repo	rt, or Other Data
NOTICE OF INTENTION TO:	1	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTE		REPAIRING WELL
FRACTURE TREAT MULTIPLE CO.		
SHOOT OR ACIDIZE ABANDON*	SHOOTING OR ACIDIZ	ABANDONMENT*
REPAIR WELL CHANGE PLAN	(Norg: Repor	t results of multiple completion on Well
(Other)	Completion or	Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Cle proposed work. If well is directionally drilled, nent to this work.) *	early state all pertinent details, and give pertinet give subsurface locations and measured and tru	nt dates, including estimated date of starting any ne vertical depths for all markers and zones perti-

Original Information:

Completed 2-14-75, TD 2211, PBTD 2177, 8-5/8@ 20# at 314'/175 Sx, 2-7/8" 6.5# at 2206 w/275 Sx. Perf 2108-1/2-20. Well depleted. Form 9-331 to plug submitted 3-18-81.

We still plan to plug as follows:

- 100' cement plug across 2177-2077.
- Unscrew 2-7/8" at 350'. 100' plug from 350' to 250'. 2.
- 10 sx at surface inside 8-5/8". Erect 4' steel marker with G. GEOLOGICAL SHOWN 1005 NEW MEAN OF THE STATE OF 3. location information. Clean location.

TITLE Geologist	DATE 4-26-82
TITLE	DATE
Instructions on Reverse Side	
	TITLE Geologist TITLE Instructions on Reverse Side

MAY 8 1982
HOSS CARICE