

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
POST OFFICE BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-745

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS)

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

1. OIL	GAS	
WELL <input checked="" type="checkbox"/>	WELL <input type="checkbox"/>	OTHER

7. Unit Agreement Name
-

2. Name of Operator
Read & Stevens, Inc.

8. Farm or Lease Name
Sun "16" State

3. Address of Operator
Post Office Box 1518, Roswell, New Mexico 88202

9. Well No.
1

4. Location of Well
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE West LINE. SECTION 16 TOWNSHIP 8S RANGE 31E NMPM

10. Field and Pool, or Wildcat
Siete San Andres

5. Elevation(Show whether DF,RT,GR,etc.)
4220.5'GR

12. County	XXXXXXXXXXXXXXXXXXXX
Chaves	XXXXXXXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:


SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-24-86 Pull rds, pmp & tbq, set CIPB @ 3706'. Prep to P&A.
1-25-86 Spot 5sx cmt on top of CIBP, pull 4jts tbq, circ hole w/Brine mud
1-26-86 Clean loc. Prep to move tanks.
1-28-86 Spot 25sx Class "C" 1200'-1000', spot 10sx surf plug 30'-0', inst dryhole marker, cutoff wellhead, cutoff deadmen, dismtl tank btry.
1-29-86 Strip out elec serv, move tank off loc, drug loc, ready for insp.
1-30-86 Clean up equip, put in stock.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. J. Stevens TITLE Drilling and Production Manager DATE February 4, 1986

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR TITLE DATE FEB 10 1986

CONDITIONS OF APPROVAL, IF ANY:

Jack Griffin



RECEIVED
FEB - 6 1986
HOBBS OFFICE