ENERGY AND MINERALS DEPARTMENT	
DISTRIBUTION QIL CONSERVATION DIVISION RECEIVED BYP. O. OX 2088 SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-7
U.S.G.S. LAND OFFICE OPERATOR O. C. D.	State X Fee 5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	K-3189
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL A GAB WELL OTHER- 30 05 405 3	7. Unit Agreement Name
MWJ PRODUCING COMPANY	8. Form or Lease Name Chaveroo "B" State
1804 First National Bank Bldg Midland, Texas 79701	9. Well No.
. Location of Well	1 1C. Field and Pool, or Wildcat
UNIT LETTER H 1650 FEET FROM THE NORTH LINE AND 330 FEET FROM	Chaveroo (San Andres)
THE East LINE, SECTION 2 TOWNSHIP 8S MANGE 32E NMPW	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
6. Check Appropriate Box To Indicate Nature of Notice, Report or Ot	Chaves
	ther Data T REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB	ALTERING CASING PLUG AND ABANDONMENT X
OTHER	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	
5/6/86: MI & RU. Pulled & LD rods and pump. SD ON. 5/7/86: RU CRC. Rnn and set CIBP @ 4150' & dumped 35' cement on to bbls of mud. Perf'd squeeze hole at 430'. RD CRC. Brk ci w/100 sx Class "C" down 4-1/2" casing, circulate thru perfo backside. Removed head & cut off casing 4' below ground dry hole marker, welded on plate. Well Plugged and Abandon	op. Loaded hole w/50 reculation and cemented orations at 430' and up
	•
. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Ja Mhno 10.	
TITLE Pat Drexler - Agent	DATE 5/9/86
Billy E. Frulow Field Rep	5/9/86