NO. OF COPIES RECEIVED		<u> </u>
DISTRIBUTION		Form C-103
		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION CO	OMMISSION Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee XX
OPERATOR		5. State Oil & Gas Lease No.
		Fee
SUNDRY  (DO NOT USE THIS FORM FOR PROPE  USE "APPLICATION	NOTICES AND REPORTS ON WELLS SSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFER N FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
I.  OIL XX GAS WELL	OTHER•	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Harvey E. Yates Co	ompany, Inc.	Graves
3. Address of Operator		9. Well No.
Suite 1000 Securif	ty Nat'l Bank Bldg., Roswell, N.M	M. 88201 #2
4. Location of Well	J Has I bain blagt, Roshell, II.	10. Field and Pool, or Wildcat
	10001	
UNIT LETTER,	FEET FROM THE 1980 LINE AND	South FEET FROM Siete-San Andres
THE 1980 LINE, SECTION	6 TOWNSHIP 85 RANGE	31E NMPM (
	15. Elevation (Show whether DF, RT, GR, etc.	c.) 12. County
	4194.6 GL	Chaves \\\\\\\\
Check Ap	opropriate Box To Indicate Nature of Not	ice, Report or Other Data SUBSEQUENT REPORT OF:
NOTICE OF INT		SUBSEQUENT REPORT OF.
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORL	K ALTERING CASING
$\overline{}$		<del></del>
TEMPORARILY ABANDON	COMMENCE DRII	
PULL OR ALTER CASING		ND CEMENT JQB [X] Run Casing
	OTHER 1	tun custing
OTHER	L_	
	ations (Clearly state all pertinent details, and give pe	rtinent dates, including estimated date of starting any proposed
	- 1	rtinent dates, including estimated date of starting any proposed
17. Describe Proposed or Completed Oper work) SEE RULE 1103.  Spudded 11" hole 5:00 Ran 349' 8 5/8" 20# conditions and circulated 20 sac	PM 10-3-76 casing, set and cemented with 120	sacks Cement. Plug down 10-4-76
17. Describe Proposed or Completed Operwork) SEE RULE 1103.  Spudded 11" hole 5:00 Ran 349' 8 5/8" 20# conditions and circulated 20 sac the plug 10-4-76. Ca	PM 10-3-76 assing, set and cemented with 120 ks cement to the pit. Waited on	sacks Cement. Plug down 10-4-76 cement 18 hours and drilled out 90# pressure for 30 minutes.
17. Describe Proposed or Completed Operwork) SEE RULE 1103.  Spudded 11" hole 5:00 Ran 349' 8 5/8" 20# conditions and circulated 20 sac the plug 10-4-76. Ca	PM 10-3-76 casing, set and cemented with 120 cks cement to the pit. Waited on sing was pressure tested with 80	sacks Cement. Plug down 10-4-76 cement 18 hours and drilled out 10# pressure for 30 minutes.
17. Describe Proposed or Completed Oper work) SEE RULE 1103.  Spudded 11" hole 5:00 Ran 349' 8 5/8" 20# cand circulated 20 sac the plug 10-4-76. Ca	PM 10-3-76 casing, set and cemented with 120 cks cement to the pit. Waited on sing was pressure tested with 80 cove is true and complete to the best of my knowledge  TITLE Vice Presigned by	sacks Cement. Plug down 10-4-76 cement 18 hours and drilled out 10# pressure for 30 minutes.  and belief.
17. Describe Proposed or Completed Oper work) SEE RULE 1103.  Spudded 11" hole 5:00 Ran 349' 8 5/8" 20# condition and circulated 20 sac the plug 10-4-76. Ca	PM 10-3-76 casing, set and cemented with 120 cks cement to the pit. Waited on sing was pressure tested with 80 cove is true and complete to the best of my knowledge  TITLE Vice Presigned by	sacks Cement. Plug down 10-4-76 cement 18 hours and drilled out 10# pressure for 30 minutes.



- -