	1		Form C-103 Supercadae Old
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION		Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5. State Oil & Gas Lease No. NM 5144
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
1. OIL X GAS WELL X	OYHER-		7. Unit Agreement Name
2. Name of Operator			8, Form or Lease Name
Champlin Petroleum Company 3. Address of Operator			State '4'
P. O. Box 7946, Midland, TX 79708-0946			4
4. Location of Well UNIT LETTER H 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM			10. Field and Pool, or Wildcat Chaveroo (San Andres)
1			
THE East LINE, SECTION	on 4 TOWNSHIP 8-S	RANGE 33-E NMPM.	
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
4408 GR Check Appropriate Box To Indicate Nature of Notice, Report or Oth			Chaves ()
Check A NOTICE OF IN			er Data REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	 -	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
OTHER		OTHER	
17. Describe Proposed or Completed Op-	erations (Clearly state all pertinent deu	ails, and give pertinent dates, including	estimated date of starting any proposed
work) see RULE 1703. RUSU 1/16/84 - RIH w/4-1/2" CIBP on WL & set @ 4100' to abandon San Andres perfs 4245-			
4346' - POH w/WL - GIH w/2-3/8" tbg to 4100' - displace hole w/10#/gal SW mud - spot 4			
sx cmt plug on CIBP - TOC @ 4039' - POH w/tbg - ran free-point - made cut in 4-1/2" prod			
csg @ 2000' - POH w/2000' 4-1/2" prod csg - RIH w/2-3/8" tbg OE to 2060' - spot 60 sx cmt			
plug from 2060 - 1837' to cover 4-1/2" prod csg stub 0 2000' & 8-5/8" surface csg shoe			
@ 1928' - WOC - RIH w/WL to 2000' - could not tag cmt plug - POH w/WL - RIH w/2-3/8"			
tbg - tagged plug 0 2010' - spot 80 sx cmt plug 2010 - 1760' - WOC - tag cmt plug 0			
1808' - POH w/tbg - spot 10 sx cmt plug @ surface - install dry hole marker - will			
cover up pits when drie			
TD @ 4505' - 4-1/2" pro	od csg set @ 4504' - 250	04' 4-1/2" prod csg left	: in hole -
8-5/8" surface csq set	@ 1928' - all of surfac	e csg left in hole.	
•			
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED MA STATE	TITLE F	roduction Engineer	1/30/84
() (h)	778	I & CAC DYON	∩∩T o ∩ 1007
APPROVED BY HELE EST	fifu TITLE OI	L & GAS INSPECTOR	OCT 3 0 1987

