

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Champlin Petroleum Company		5. State Oil & Gas Lease No. K-2734
3. Address of Operator 300 Wilco Building, Midland, Texas 79701		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>14</u> TOWNSHIP <u>8-S</u> RANGE <u>33-E</u> NMPM.		8. Farm or Lease Name Conoco "14" State
		9. Well No. 1
		10. Field and Pool, or Wildcat Chaveroo-San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4462' Gr.		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was Plugged and Abandoned as follows:

4-21-77 Set CIBP @4174' with 50' of cement on top.
4-22-77 Shot 4-1/2" casing off @3326'. Set 45 sacks plug in & out casing stub from 3376 to 3276'.
4-26-77 Set 50 sack plug in and out surface pipe 1898 to 1777'.
4-28-77 Set 10 sack plug in top of surface pipe.
Installed Dry Hole Marker.
Hole loaded with 10# Mud w/gel.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter S. Randolph TITLE District Clerk DATE May 27, 1977
APPROVED BY Nathan E. Clegg TITLE OIL & GAS INSPECTOR DATE SEP 21 1978
CONDITIONS OF APPROVAL, IF ANY: