

7. METHODS OF HANDLING WASTE DISPOSAL:

- A. Waste will be buried in reserve pits at a depth of 24". The well site will be cleaned of all waste and this will be done within 10 days after completion of the well.

8. ANCILLARY FACILITIES:

- A. None required

9. WELLSITE LAYOUT:

- A. Please refer to Exhibit "C" on which is shown the configuration of a WEK Drilling Company rig. The well site will need no unusual amount of cut or fill. We do not plan to line reserve pits.

10. PLANS FOR RESTORATION OF THE SURFACE:

- A. If the well is completed as a producing well, we will knock down pits and smooth out the surface. If not productive, in addition to the above, we will level the location.

11. OTHER INFORMATION:

- A. The planned access road and the pad will be located on relatively flat land with no extreme cuts required. There are no houses, ponds, streams or lakes in the vicinity of the proposed location. There is a windmill located in Section 1, Unit 1.
- B. The surface owner is Dillard Nuckols and arrangements have been made with him as to surface damage payment.

12. LESSEE'S OR OPERATOR'S REPRESENTATIVE:

- A. The responsible field representatives are as follows:

Drilling Fred G. Yates
 Harvey E. Yates Company, Inc.
 Suite 1000 Security National Bank Building
 Roswell, New Mexico 88201
 Office Phone: 505-623-6601
 Mobile Phone: 623-0989 Unit #327-4109
 Home Phone: 505-622-5387

Production Herbert Spencer
 H & S Oil Company
 216 American Home Building
 Artesia, New Mexico 88210
 Office Phone: 505-746-6658
 Mobile Phone: 365-2504
 Home Phone: 505-746-2495