## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240  OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 2088  DISTRICT II  P.O. Drawer DD. Artesia NM 88210  Santa Fe, New Mexico 87504-2088	230 005 20614
P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE 6. State Oil & Gas Lease No.
	U. State Oil & Oas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Weil:	State DQ
WELL X WELL OTHER	
Name of Operator	8. Well No.
Southwest Royalties  Address of Operator	9. Pool name or Wildcat
P.O.BOX 11390, Midland, Tx. 79702	Many Gates (Wolfcamp)
. Well Location	
Unit Letter C: 660 Feet From The North Line and 1980	Feet From The West Line
Section 32 Township 9s Range 30 E	Chaves
10Wnship 53 Range 50 L	NMPM Chaves County
	<i>\{\/\/\/\/\/\/\/\/\/\/\/\/\/\/\/\/\/\/\</i>
Check Appropriate Box to Indicate Nature of Notice, Re	eport, or Other Data
	SEQUENT REPORT OF:
REFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT X
JLL OR ALTER CASING CASING TEST AND CE	<u></u>
CASING TEST AND CE	MENT JOB
THER: OTHER:	MENT JOB
THER: OTHER:	MENT JOB
OTHER:	MENT JOB
THER:	MENT JOB
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25	MENT JOB  ling estimated date of starting any proposed  sx. cement @7250 to 6984
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called the said to spot plug @5822, 4157, 1676, & 8	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called the said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called the said to spot plug @5822, 4157, 1676, & 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called the said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cwmwnt @1676 to 1423	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, calle He said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cwmwnt @1676 to 1423 8. 7/21/98 Spot 50 sx. cement @838	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, calle He said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cwmwnt @1676 to 1423 8. 7/21/98 Spot 50 sx. cement @838 9. 7/22/98 Tag cement @ 693	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D. 38. Tag plug@838
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, calle He said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 50 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. temporary contents and contents and contents are contents are contents and contents are contents and contents are contents and contents are contents and contents are contents are contents and contents are contents are contents and contents are contents are contents are contents are contents and contents are contents and contents are contents are contents and contents are	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D. 38. Tag plug@838
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, calle He said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cwmwnt @1676 to 1423 8. 7/21/98 Spot 50 sx. cement @838 9. 7/22/98 Tag cement @ 693	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D. 38. Tag plug@838
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, calle He said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 50 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. temporary contents and contents and contents are contents are contents and contents are contents and contents are contents and contents are contents and contents are contents are contents and contents are contents are contents and contents are contents are contents are contents are contents and contents are contents and contents are contents are contents and contents are	ing estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D. 38. Tag plug@838
THER:  2 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called the said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cwmwnt @1676 to 1423 8. 7/21/98 Spot 50 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. the land of the best of my knowledge and belief.	ment Job  ling estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D. 38. Tag plug@838
OTHER:  2 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, calle He said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. the state of my knowledge and belief.	ment Job  ling estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D. 38. Tag plug@838
THER:  2 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called 0.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called He said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cwmwnt @1676 to 1423 8. 7/21/98 Spot 25 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. the hereby certify that the information above is true and complete to the best of my knowledge and belief.  HERE:    OTHER:	ment Job  ling estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D. 38. Tag plug@838  o surface tole marker
THER:  2 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, calle He said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. to 11. 7/23/98 Cut off well head, install dry hearth of the centre of the best of my knowledge and belief.  Hereby certify that the information above is true and complete to the best of my knowledge and belief.  HONATURE And the information above is true and complete to the best of my knowledge and belief.  HONATURE And the information above is true and complete to the best of my knowledge and belief.  HONATURE And the information above is true and complete to the best of my knowledge and belief.  HONATURE And the information above is true and complete to the best of my knowledge and belief.  HONATURE And the information above is true and complete to the best of my knowledge and belief.  HONATURE And the information above is true and complete to the best of my knowledge and belief.	ment Job  ling estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D. 38. Tag plug@838
THER:  2 Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called the said to spot plug @5822, 4157,1676, & 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cwmwnt @1676 to 1423 8. 7/21/98 Spot 25 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. to 11. 7/23/98 Cut off well head, install dry hearth of the post of my knowledge and belief.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.	ment Job  ling estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/O.C.D. 38. Tag plug@838  so surface tole marker  April 2/23/98
THER:  2 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called the said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @1676 to 1423 8. 7/21/98 Spot 50 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. to 11. 7/23/98 Cut off well head, install dry head, install dry head.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  WINATURE Wayner Bright Name	ment Job  ling estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/O.C.D. 38. Tag plug@838  so surface tole marker  April 2/23/98
THER:  Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called 0.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, calle He said to spot plug @5822, 4157, 1676, & 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @1676 to 1423 8. 7/21/98 Spot 50 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. the state of the content of the	ment Job  ling estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/O.C.D. 38. Tag plug@838  so surface tole marker  April 2/23/98
THER:  2 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include work) SEE RULE 1103.  1. 7/14/98 Called O.C.D. move in 2. 7/15/98 Set CIBP @7250 3. 7/18/98 Circulate hole w/9.8 mud, spot 25 4. 7/20/98 Cut 5½ @5753, could not pull, called He said to spot plug @5822, 4157,1676,& 8 5. 7/21/98 Spot 25 sx. cement @5822 to 5569 6. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @4157 to 3904 7. 7/21/98 Spot 25 sx. cement @1676 to 1423 8. 7/21/98 Spot 50 sx. cement @838 9. 7/22/98 Tag cement @ 693 10. 7/22/98 Spot 20 sx. cement from 30 ft. to 11. 7/23/98 Cut off well head, install dry head.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  The Plagaine Title Plagaine  The Plagaine Title Plagaine  The Plagaine Title Plagaine	ment Job  ling estimated date of starting any proposed  sx. cement @7250 to 6984 d Jack Griffin w/0.C.D. 38. Tag plug@838  o surface tole marker  Page 1/23/98  TELEPHONE NO.