

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5606

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>
1. Name of Operator Amoco Production Company
2. Address of Operator P. O. Box 68 - Hobbs, NM 88240
3. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>9-S</u> RANGE <u>30-E</u> NMPM.

7. Unit Agreement Name
8. Farm or Lease Name State DQ
9. Well No. 1
10. Field and Pool, or Wildcat Many Gates Morrow

15. Elevation (Show whether DF, RT, GR, etc.)	12. County Chaves
---	----------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in service unit 10-3-80. Set a cast iron bridge plug at 9100'. Capped with 35' cement. Perforated 8114'-8128' and 7292'-7320' with 4 JSPF. Set a bridge plug at 8250' and set packer at 7997'. Acidized with 2800 gal. 20% DS-30 acid with additives. Swabbed three days and recovered no oil and no gas. Set bridge plug at 7507'. Set packer at 7125'. Acidized with 5600 gal. 20% DS-30 acid with additives. Currently swab testing.

0 + 4 - NMOCD, H 1-Hou 1-LBG 1-Susp 1-W. Stafford, Hou

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst. Admin. Analyst DATE 10-21-80

APPROVED BY Diat L. Supt. TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

M