

UNITED STATES
DEPARTMENT OF THE INTERIORSUBMIT IN TRIPlicate
(Other instruction
verse side)When approved,
District Office No. 42-11424
5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY

NM000 - ARTESIA

NM000 - 11424

BLM - 3111E

SUDDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)NM 0403741-A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME1. OIL WELL ☒ GAS WELL ☐ OTHER ☐7. UNIT AGREEMENT NAME
None

2. NAME OF OPERATOR

8. FARM OR LEASE NAME

Charles B. Read

Shell-Federal

3. ADDRESS OF OPERATOR

9. WELL NO.

P.O. Box 2126, Roswell, New Mexico 88201

10. FIELD AND POOL, OR WILDCAT

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface11. SEC., T., R., PT., OR COR. AND
SURVEY OR AREA

660' FSL & 660' FEL of Sec. 13, Twp 8S, Rge 31E NMPM

13-8S-31E

14. PERMIT NO.

15. ELEVATIONS (Show whether LF, RT, GR, etc.)

12. COUNTY OR PARISH

13. STATE

4407' GL

Chaves

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As per telephone conversation with Mr. Ronnie Schoak on 10/9/68, we intend to plug and abandon in the following manner:

Set 10 sx	surface plug	0' - 10'
30 sx	plug	300' - 400'
30 sx	plug	1600' - 1700'
30 sx	plug	3250' - 3350'
25 sx	plug	4000' - 4085'

Erect location marker.

Make clean up.

RECEIVED

OCT 21 1968

U.S. GEOLOGICAL SURVEY
ROSSELL, NEW MEXICORECEIVED
OCT 18 1968
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE 10/16/68

(This space for Federal or State office use)

APPROVED BY
APPROVAL, IF ANY:

TITLE

DATE

OCT 21 1968

J. W. GUTERLAND
DISTRICT ENGINEER

*See Instructions on Reverse Side