

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L - 4410

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>	7. Unit Agreement Name
2. Name of Operator <u>Miller Oil Company</u>	8. Farm or Lease Name <u>Miller State</u>
3. Address of Operator <u>3612 West Wall, Midland, Texas 79701</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>C</u> , <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>1880</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>8-S</u> RANGE <u>32-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4367 Gr. , 4382 KB.</u>	12. County <u>Chaves</u>

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 50 sk. plug 9510'. Tagged plug @ 8678'.
2. Circulated hole with mud.
3. Pulled 4½" casing from 5005 and laid down same.
4. Ran tubing to 5070, spotted a 50 sk. plug. WOC. Tagged plug at 5010.
5. Pumped 35 sk. plug from 5010 to 4910.
6. Pulled tubing 3610 and spotted 40 sk. plug. WOC and tagged plug at 3501.
7. Pulled tubing to 1790'. Spotted 35 sk. plug to 1690. Pulled out of hole. Cut off well head. Spotted 10 sk. surf. plug. Installed dry hole marker. Rig down.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>[Signature]</u>	TITLE <u>P & A Contractor</u>	DATE <u>9-27-78</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>9-27-78</u>
CONDITIONS OF APPROVAL, IF ANY:		