

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
3. State Oil & Gas Lease No. LG 1774	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPLY OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator MWJ Producing Company		8. Farm or Lease Name Chaveroo State
3. Address of Operator 1804 First Nat'l. Bank Bldg. Midland, Texas 79701		9. Well No. 7
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>8S</u> RANGE <u>32E</u> N.M.P.M.		10. Field and Pool, or Wildcat Chaveroo San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4471.6' Gr.		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <u>Log Perf. & Acidize</u> <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Pressure tested 4 1/2" casing to 4,000 psi. Held Ok. RU and Ran CNL & GR Logs from 4337' to Surface. Perf'd. as follows: 4213, 19, 23, 26, 33, 39, 61, 63, 66, W/2 SPF and 4278-4290' W/2 SPF, 4294, 4303, 08, 14, 21, 27, and 4335' W/2SPF. Ran tubing in hole and spotted 500 gallons 28% Acid. Packer set at 4150'. Broke formation and acidized with 2,000 gallons 20% HCL Acid plus 72 ball sealers. Flushed with fresh water. Swab to pit for 5 hrs. and swabbed to tank for 1 hr. Ran tubing pump and rods. Now testing on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 7/20/81

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: