

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 31263

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Holbrook ~~Federal~~ "B" *Federal*

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Vest Ranch-Queen Assoc.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

9-15S-30E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Dalport Oil Corporation

3. ADDRESS OF OPERATOR

3471 First National Bank Bldg., Dallas, Tx. **RECEIVED**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660 1650
1650' FSL - 990' FWL

AUG 11 1980

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZING ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐ Production casing

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-4-80 TD 2365 Ran 60 joints new 4½" - 9.5# J-55 casing. 20' joint on bottom with float shoe, automatic insert at top of bottom joint. Three 40.3 joints with 1 centralizer and 3 scratchers/joint. One 22' joint. Halliburton cemented with 10 bbls mud flush, 125 Sx lite, 150 Sx 'C', 50% Poz, 8# salt per sack, 2% gel. 50 gal. acetic acid. Plug down 11:45 PM.

Will WOC 48hrs. Run gamma-neutron log and perforate Queen with casing gun.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE 8/8/80

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DATE

AUG 12 1980

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

AUG 15 1980

RECEIVED

AUG 15 1980

O. C. D.
ARTESIA OFFICE

RECEIVED

AUG 20 1980

WILDERNESS DIV.