STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION		
SANTA FE		
FILE		_
U.1.0.1.		<u> </u>
LAND OFFICE		
00104100	7	1

Original signed by Paul Kautz

OIL CONSERVATION DIVISION .P. O. BOX 2088

Form C-103 Revised 19-1-78

April 6, 1981

JAN 2 4 1985

SANTA FE			SANTA FE, N	NEW A	MEXICO B7	501				
FILE		ĺ	J				ſ	Se. Indicate Ty	pe of Lesi	. •
V.1.0.1.		{					1	State	•	Гөө 🗓
LAND DIFICE		ſ					ļ	5. Stole Oli &	<u> </u>	
DPERATOR		†					;	5. Stole Ol. 6	CG2 _ FUNW	
077770		,	`	•					\overline{m}	m
	SUNDR	Y NOTICES	AND REPORTS	S ON W	ELLS	RECEIVED				
(DO MOT USE 7 HT			(FORM C-101) FO			· ·		7. Unit Agreen	nent Hame	7777777
1.	•••						. 1	3		
	###. <u> </u>	07 m E # -				R-0-8- 198	1	8. Form or Le	ase liame	,
2. Name of Operator		_	7. 0 M	Mr. 3	Shir	2100	12	. W. Cato		
Coronado	Explorat	ion Corp.	Ciball		Co/lury	sid Di	Seft.	W. Cato		
3. Address of Operator				٠, .	. ART	ESIÁ, OFFICE	: [/	1		
1005 Mar	quette NW	Alb	uquerque, Ne	ew Me	x1co			10. Field and	Dool or W	Hdcat
4. Location of Well						•		10, Fleid Cand	P001, 01 W	110001
	Н	1980	T FROM THE Nor	th	1 INC AND	660	TEET FROM	Und. Ca	to SA	\overline{m}
UNIT LETTER	··-	-1900 711	T FROM THE							///////
_		1.0		85	94465	30E				
East	LINE, SECTI	o= <u>18</u>	TOWHSHIP		4A+6E					711111.
	mm		Elevation (Show wi	hether D	F. RT. GR. etc	.)		12. County		IIIIII
		///////////////////////////////////////	4092.0			•		Chaves		//////
		111111								******
16.	Check	Appropriate	Box To Indica	ate Na	sture of Not	ice, Repoi	rt or Oth	er Data		
N.C	TICE OF I	NTENTION	TO:	1		. subs	EQUENT	REPORT C	F:	
•••	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			- 1						_
		-	PLUG AND ABANDON		REMEDIAL WORK	L		AL	TERING CAS	.>=6
PERFORM REMEDIAL WOR	⁺∺				-	0748.		PL	UE AND ABA	HDOHMENT L
TEMPORARILY ABANDON	\vdash				CABING TEST AN			•		_
PULL OR ALTER CASING	L		CHANGE PLANS	니	ОТИЕЯ					[
	•				V					
#THER									<u> </u>	
17. Describe Proposed	Campleted C	mentions (Clea	arly state all pertine	eni deia	ils, and give pe	rtinent dates.	including	estimated date	of starting	eny propos
17. Describe Proposed (fos.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								
311-81			<u>.</u>						~	
J-11-01				-1 6	: / 1/2!! -	acina an	d nlugg	and the we	11 as	
Ran free	point ar	nd cut and	d pulled 266	2, or	: 4 1/2 C	asing an	d bragi	ged the we	.11 40	
follows		•								
	Plug #1	3320	- 3180'		35 sx					
	Plug #2	2680-	-tagged 2630	•	70 sx					•
	Plug #3		- 2444'		35 sx					
			- 1948		35 sx				•	
	Plug #4	1072	- 1940 t-aged 9!	991	35 sx					
	Plug #5		- tagged 98			CV				
	Plug #6	Dry	hole marker	at st	illace 10	J.				
					ووالمراسية	for inc	nectic	n by 4-20.	-81	
Pits wi	ll be lev	eled and	location cle	aned	and ready	101 1118	PCCLIO	. 5, 4 20	-	
•	•						•			
			•		•					
								-		
				,						
	•			:		•				
		ab au - 1a 4	and complete to th	he best 4	of my tnowledge	and belief.				
	a about of the	on spoye is if w	IN COMPLETE TO IT	'						

Production Secretary