

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. OIL & GAS COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

Modified Form No.
NM-0-3160-4

LEASE DESIGNATION AND SERIAL NO.

NM 67707

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		2. NAME OF OPERATOR Petroleum Development Corporation	3. Acre Code & Phone No. (505) 293-4044	4. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 9720 B Candelaria N.E. Albuquerque, NM 87112		5. FARM OR LEASE NAME Siete Federal		6. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FEL of Section 17.		7. WELL NO. 1		8. FIELD AND POOL, OR WILDCAT Siete San Andres
14. PERMIT NO.		15. ELEVATION (Show whether OF, AT, OR, ETC.) 4211' GR		9. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17. T8S. R31E
				10. COUNTY OR PARISH Chaves
				11. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANE	☐
(Other)	Horizontal Drill		X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Set CIBP @ 3704'.
 2. Mill out 5½" casing from approx. 3670' to 3700'.
 3. Set cement kick off plug.
 4. Drill 40' radii arc to 3720'.
 5. Horizontally drill 270' ± from 3720' to 3751'.
- (The horizontal hole will not be closer than 330' to any boundary of the 40 acre spacing tract.)

Build a working pit 40' north of existing well where old reserve pit was located.
Dimensions as follows:

20' wide x 70' long x 5' deep.



18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Production Manager

DATE 10-25-90

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

SUBJECT TO LIKE
APPROVAL BY STATE

NOV 13 1990

*See Instructions on Reverse Side

