

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator <u>Armstrong Energy Corporation</u> 3. Address of Operator <u>P.O. Box 1973 - Roswell NM 88201</u> 4. Location of Well UNIT LETTER <u>J</u> <u>1980'</u> FEET FROM THE <u>South</u> LINE AND <u>1980'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>11S</u> RANGE <u>31</u> <u>30S</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <u>4514'</u> GL 12. County <u>Chaves</u>	7. Unit Agreement Name 8. Farm or Lease Name <u>Sara</u> 9. Well No. <u>#1</u> 10. Field and Pool, or Wildcat <u>Tower San Andres</u>
---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows: August 6, 1983

Filled hole with mud-laden fluid.  
Set wireline bridge plug 4050'.  
Spot 10 sx. cement plug on B.P.  
Perforated 4 shots 1475'.  
Spot 50 sx. cement plug 1480'-1300.  
Spot 10 sx. cement plug 100'- surface.  
Install dry hole marker.

Preparing to clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mike Spinks TITLE Agent DATE 9/20/83

APPROVED BY Ronald M. Castleberry TITLE OIL & GAS INSPECTOR DATE FEB 18 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 7 1983

O.C.D.  
HOBBS OFFICE