ERGY AND MINERALS DEPARTMENT	OIL CONSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	Form C-
JANTA FE	SANTA FE, NEW MEXICO 87501	Revised
U.S.G.S.		Sa. Indicate Type of Lease
LAND OFFICE		StateF
OPERATOR		5. State Off & Gus Lease No.
SUNDRY NUTLE IDO NOT USE THIS FORM FOR PROPOSALS TO DE USE "APPLICATION FOR PERMA	ES AND REPORTS ON WELLS ALLE ON TO DIFFIN ON DUD DATA TO A DIFFERENT RESERVOIR. ALL	
		7. Unit Agreement Name
WELL OTHER-		
Dallas Production, In	с.	8. Farm or Leuse Name
dress of Operator		<u> </u>
4600 Greenville Ave.,	Dallas, TX 75206-5038	3
ocation of Well	······································	10. Field and Pool, or Wildcu
UNIT LETTER N 660	EET FROM THE South LINE AND 1650 FEET F	Chavaroo SanAndi
	1	
THE West LINE, SECTION 15	TOWNSHIP 85 RANGE 33E NM	10m. XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
sommininininininini	5. Elevation (Show whether DF. RT. GR. etc.)	12. County
	4385 DF	Chaves
Check Appropriat	e Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF INTENTION		ENT REPORT OF:
ORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PORARILY ABANDON	COMMENCE DRILLING OPHS.	
		PLUG AND ABANDONM
. OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQ8	PLUG AND ABANDONM
. OR ALTER CASING		PLUG AND ABANDOHM
THER	CHANGE PLANS CASING TEST AND CEMENT JQ8	
Pulled pump, rods and set at 4368'. Ran tul 4384-4405 with 260 sat to pressure of 1100 pi to 2500 psig. Tested 4288-4344 with 1 shot and acidized perforat	CHANGE PLANS CASING TEST AND CEMENT JQ8	wireline, tions salt/sk. ze job al
Pulled pump, rods and set at 4368'. Ran tul 4384-4405 with 260 san to pressure of 1100 p to 2500 psig. Tested 4288-4344 with I shot and acidized perforat and 85 ball sealers.	tubing. Ran cement retainer on bing and squeeze cemented perfora cks of Premium Howco cement w/ 3# sig. After 24 hours tested squee ok - perforated &n Andres interr per toot. Total 57 shots. Ran ions with 4000 gals. NE-FE-15% ac	wireline, tions salt/sk. ze job al
Pulled pump, rods and set at 4368'. Ran tul 4384-4405 with 260 san to pressure of 1100 p to 2500 psig. Tested 4288-4344 with I shot and acidized perforat and 85 ball sealers.	CHANGE PLANS casing TEST AND CEMENT JQ8 other tubing. Ran cement retainer on bing and squeeze cemented perfora cks of Premium Howco cement w/ 3# sig. After 24 hours tested squee ok - perforated &n Andres interr per toot. Total 57 shots. Ran ions with 4000 gals. NE-FE-15% ac Put well on pump - now testing.	wireline, tions salt/sk. ze job al