

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

N. M. OIL & GAS COMMISSION
SUBMIT IN TR
DATE
FORM 1004-0175
Expires August 31, 1985

Budget Bureau No. 1004-0175
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

4001 Penbrook St., Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit N, 660' FSL & 1980 FWL

14. PERMIT NO.

30-005-20847

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4439' GR

5. LEASE DESIGNATION AND SERIAL NO.
NM-0174830

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Davis -N-

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Chaveroo San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 7, 8-S, 33-E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PELL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Test all anchors. MI RU DDU. NU BOP's.
2. Set 4-1/2" CIBP @ 4200'. Circulate hole with 9.5 ppg mud-laden fluid from depth of 4200'.
3. Spot Plug No. 1 (20 sx. cement) 4000' - 4200'.
4. Spot Plug No. 2 (20 sx. cement) 3410' - 3610'.
5. Spot Plug No. 3 (20 sx. cement) 2668' - 2868'.
6. Spot Plug No. 4 (20 sx. cement) 1593' - 1793'.
7. Perforate 4-1/2" at 664'. Circulate 4-1/2" ID from surface thru perfs at 664' and back to surface on 8-5/8" x 4-1/2" annulus with Plug No. 5 (250 sx. cement) 3' - 664'.
8. Cut off casing 3' below GL. Erect monument marker and perform reclamation work.

18. I hereby certify that the foregoing is true and correct

SIGNED

John L. M. Sanders

TITLE Supv., Reg. Affairs

DATE 10/23/92

9157368-1488

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
PETER W. CHESTER

OCT 29 1992

BUREAU OF LAND MANAGEMENT
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

1.



10

1992

1992