80. 87 CAPITO BICCIIVED		ATION DIVISION		P	
DISTRIBUTION SANTA FE	P. O. BOX 2088 SANTA FE, NEW MEXICO 87501			Form C-103 Revised 10-1-	
FILE			Sa. Indicate Typ	o of Leuso Fre X	
LAND OFFICE OPERATOR			State Cti & G		
		1 WELL C			
DO NOT USE THIS FORM FOR PROPASA USE "APPLICATION F	OTICES AND REPORTS OF	N TILLUS BACK TO A DIFFERENT RESERVOIR, CH PROPOSALS.)			
OIL X GAD	DTHER-		7. Unit Agreeme	nt jvane	
2. Name of Operator Yates Energy Corporation			8. Farm or Leus Curlew 19	8. Form or Leuse Name Curlew 19	
3. Addiess of Operator Security National Bank Bldg, Suite 919, Roswell, New Mexico 88201			9. Weil No.		
Location of Well	Blag, Sulte 919, Rost	Veil, New Mexico 8820.	10, Field and Po	coi, or Wildcat	
UNIT LETTER G, 1980 FEET FROM THE North LINE AND 1980 FEET FROM			Wildcat		
THEEastLINE, SECTION	19 TOWNSHIP 85	RANGE <u>30E</u>	NMPM.		
mmmmmmm	15. Elevation (Show whethe	r DF, RT. GR, ecc.)	12. County		
6. Check Appropriate Box To Indicate Nature of Notice, Report or Ot			Chaves		
ERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	f	RING CASING [AND ABANDONMENT [
Confirming verbal a		OTHER		[
OTHER					
7. Describe Proposed or Completed Operati	ons (Clearly state all pertinent de	tails, and give pertinent dates, inc	luding estimated date of	starting any propos	
Describe Proposed or Completed Operati work) SEE AULE 1103. We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andre: All space between plugs	well as follows: . 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236	- cemented to surface - cemented up to 8 5/ '.	e. 8 5/8" casir		
We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres	well as follows: . 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud	- cemented to surface - cemented up to 8 5/ '. laden fluid.	e. 8 5/8" casir 8" casing.	ng @ 2825' -	
Work) SEE RULE 1103. We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres All space between plugs	well as follows: 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud - 2996', tag same.	- cemented to surface - cemented up to 8 5/ '. laden fluid. Cut off & salvage fre	e. 8 5/8" casir 8" casing.	ng @ 2825' -	
We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres All space between plugs Plug #1 - 20sxs - 3196'	well as follows: 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud - 2996', tag same. in and 50' above 4 1/	- cemented to surface - cemented up to 8 5/ '. laden fluid. Cut off & salvage fre 2" stub	e. 8 5/8" casir 8" casing.	ng @ 2825' -	
We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres All space between plugs Plug #1 - 20sxs - 3196' Plug #2 - 30 sxs - 50'	well as follows: 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud - 2996', tag same. in and 50' above 4 1/ e and below 13 3/8" c	- cemented to surface - cemented up to 8 5/ '. laden fluid. Cut off & salvage fre 2" stub asing shoe	e. 8 5/8" casir 8" casing.	ng @ 2825' -	
We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres All space between plugs Plug #1 - 20sxs - 3196' Plug #2 - 30 sxs - 50' : Plug #3 - 30 sxs - above	well as follows: 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud - 2996', tag same. in and 50' above 4 1/ e and below 13 3/8" c	- cemented to surface - cemented up to 8 5/ '. laden fluid. Cut off & salvage fre 2" stub asing shoe	e. 8 5/8" casir 8" casing.	ng @ 2825' -	
We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres All space between plugs Plug #1 - 20sxs - 3196' Plug #2 - 30 sxs - 50' : Plug #3 - 30 sxs - above	well as follows: 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud - 2996', tag same. in and 50' above 4 1/ e and below 13 3/8" c	- cemented to surface - cemented up to 8 5/ '. laden fluid. Cut off & salvage fre 2" stub asing shoe	e. 8 5/8" casir 8" casing.	ng @ 2825' -	
We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres All space between plugs Plug #1 - 20sxs - 3196' Plug #2 - 30 sxs - 50' : Plug #3 - 30 sxs - above	well as follows: 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud - 2996', tag same. in and 50' above 4 1/ e and below 13 3/8" c	- cemented to surface - cemented up to 8 5/ '. laden fluid. Cut off & salvage fre 2" stub asing shoe	e. 8 5/8" casir 8" casing.	ng @ 2825' -	
We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres All space between plugs Plug #1 - 20sxs - 3196' Plug #2 - 30 sxs - 50' Plug #3 - 30 sxs - above Plug #4 - 10 sxs - at su	well as follows: 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud - 2996', tag same. in and 50' above 4 1/ e and below 13 3/8" c urface and regulation	- cemented to surface - cemented up to 8 5/ laden fluid. Cut off & salvage fre 2" stub asing shoe marker.	e. 8 5/8" casir 8" casing.	ng @ 2825' -	
We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres All space between plugs Plug #1 - 20sxs - 3196' Plug #2 - 30 sxs - 50' Plug #3 - 30 sxs - above	well as follows: 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud - 2996', tag same. in and 50' above 4 1/ e and below 13 3/8" c urface and regulation	- cemented to surface - cemented up to 8 5/ laden fluid. Cut off & salvage fre 2" stub asing shoe marker. of my knowledge and belief.	e. 8 5/8" casir 8" casing. ee 4 1/2" casing	ng @ 2825' -	
We propose to plug this Plugged back T.D. 3245' cemented to surface. 4 Perforation: San Andres All space between plugs Plug #1 - 20sxs - 3196' Plug #2 - 30 sxs - 50' Plug #3 - 30 sxs - above Plug #4 - 10 sxs - at su	well as follows: 13 3/8" csg @ 321' 1/2" casing @ 8670' s Pl Zone 3196'- 3236 to be left with mud - 2996', tag same. in and 50' above 4 1/ e and below 13 3/8" c urface and regulation	- cemented to surface - cemented up to 8 5/ laden fluid. Cut off & salvage fre 2" stub asing shoe marker.	e. 8 5/8" casir 8" casing. ee 4 1/2" casing	ng @ 2825' -	

CONDITIONS OF APPROVAL, IF ANY:



. •