

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ WELL GAS ☒ WELL OTHER-	7. Unit Agreement Name Curlew Unit 19
2. Name of Operator Harvey E. Yates Company	8. Farm or Lease Name
3. Address of Operator P. O. Box 1936, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>19</u> TOWNSHIP <u>8S</u> RANGE <u>30E</u> N.M.P.M.	10. Field and Pool, or Wildcat Wildcat
11. Elevation (Show whether DF, RT, GR, etc.) -055.2' GL	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☒
OTHER Ran 13 3/8" & 8 5/8" csg ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/18/82 Depth 321'. RU & Ran 13 3/8" ST&C
1 jt 13 3/8" 48# ST&C 20.70'
8 jts 13 3/8" 54# ST&C 315.05
335.75'

Cmtd w/325 sx Class "C" plus 1/4# per sx flocele & 2% CaCl. Circ 70 sx to pit.
PD 12:30 p. m.

3/19/82 After 18 hrs WOC tested 13 3/8" csg to 1000#/30 min.

3/24/82 Depth 2800'.

3/25/82 Ran 69 jts 8 5/8" csg.

10 jts 32# 8 5/8" ST&C	426.43'
58 jts 24# 8 5/8" ST&C	2358.24'
1 jt 32# 8 5/8" ST&C	40.33'
	2825.00'

Set @ 2800' (shoe jt of 42.5'). Cmtd w/1600 sx Howco Lite plus 4# salt, 5# Gilsonite & 1/4# flocele per sx. Tail in w/200 sx Class "C" plus 1/4# flocele per sx & 2% CaCl. Pumped plug w/500# over press. Cmt did not circ. 1" w/250 sx Class "C" plus 2% CaCl. Circ 10 sx to pit. WOC 11 1/2 hrs.

3/29/82 WOC 23 1/2 hrs. NU Casing Spool & BOP. Tested BOP & 8 5/8" csg to 1500 pai. 30 min held o. k.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rich Hardie

TITLE Engineer

DATE 4/02/82

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 5 1982

O.C.D.
HOBBS OFFICE