MN OIL CONS. COMMISSIC. Hells Drawer DD

Form Approved. Budget Bureau No. 42-R1424

Artesia. NM

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY		5. LEASE NM-150/6 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REP (Do not use this form for proposals to drill or to d reservoir, Use Form 9–331–C for such proposals.)	PORTS ON WELLS.	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil gas cother other	FEB 27 1986	NATTAM FEDERAL. 9. WELL NO.
2. NAME OF OPERATOR EXXON CORPORATI	O. C. D.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR BOX 1600, MIDLAND TEXAS 7970 2 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 660 FSL AND 660 FEL OF SEC AT TOP PROD. INTERVAL: AT TOTAL DEPTH:		1 SEC T T. 8-5 R-31E
16. CHECK APPROPRIATE BOX TO INDIC		15. ELEVATIONS (SHOW DF, KDB, AND WD) 4202 CK.
REQUEST FOR APPROVAL TO: SUB TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON*	SEQUENT REPORT OF:	(NOTE: Report results of multiple completion or zone change on Form 9–330.)

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- 1. PULLED RODS AND TUBING. CIRE W/WIND LADEN FLWID.
- 2. SET CIBPAT 3255'- SPOT USX CMT AT 3255!
- 3. POH TO 1298-SPOT 203x CMT PLUG. POH TO 400'- SPOT 455X CNIT PLUG. SPOT 55X CMT PLUG AT SURFACE
- 4. INSTALLED DRY HOLE MARKER. CLEANED LOCATION.

Subsurface Safety Valve: Manu. and Type	Set @Ft.		
18. I hereby certify that the foregoing is true and correct	1. ADMIN DATE 9-3-85		
APPROVED BY PETER W. CHESTER his space for Fe	deral or State office use) DATE		
BUREAU OF LAND MANAGEMENT	•		
BUREAU OF LAND MANAGE AREA ROSWELL RESOURCE AREA *See Instruction	ions on Reverse Side		

3 D 13

MAR 3 1986