Form 9-331 Dec. 1973

ABANDON\*

(other)

-----

## MM OIL CONS. COMMISSION Drawer DD

## UNITED STATES 12, NM 88210

## DEPARTMENT OF THE INTERIOR

Form Approved.			
Budget	Bureau	Nο	42-R142

	15165			 
5.	LEASE			
	NM	_	19197	

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME   8. FARM OR LEASE NAME
1. oil gas other Abandoned	Phillips Federal  9. WELL NO.
2. NAME OF OPERATOR  Mineral Development, Inc.  3. ADDRESS OF OPERATOR TWO Midland National	2 10. FIELD OR WILDCAT NAME East Siete S.A. (Ext.)
Center Suite 965 Midland, Texas 79701  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.) AT SURFACE:660' FSL & 1980' FEL of Sec. 15. AT TOP PROD. INTERVAL:	Sec. 15 - 8S - 31E  12. COUNTY OR PARISH 13. STATE  Chaves NM
AT TOTAL DEPTH:  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 4274' GL & 4278.5 KB
REQUEST FOR APPROVAL TO:  TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  SUBSEQUENT REPORT OF:  U  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	3 1983 change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

MINERALS MOMT. SERVICE

ROSWELL, NEW MEXICO

Abandoned subject well by spotting cement plugs by circualtion as follows:

		Plug #	DP depth	Sacks Cmt.	Depth Cement Plug
	RECEIVED BY		4000'	90	4000 - 3550
١	DEC 01 1983		1953'	120	1953 - *1805'
١	0 C. D.	4	1409'	120	1409 - *1072:
	O. C. D. ARTESIA, OFFICE		30'	20	30: -** surface
1		Install well marker	Dlan to stant cloan	up on 2-21-83	

Install well marker. Plan to start clean up on 2-21-83.

* Tag top of plug w/drill pipe	
** Cement circ to surface	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED W. J. Mother TITLE V.P. Prod.	DATE2-18-83
APPROVED (This space for Federal or State office use)	
(Orig. Sgd.) PETER W. CHESTER APPROVED BY	DATE
NOV 2 9 1983	

DEC 5 1983
HOSES CORRECT