-

Drawer DD Artesia. EX

8821

Form Approved. Budget Bureau No. 47-R1424

UNITED STATES

DEPARTMENT OF THE INTERIOR ___

GEOLOGICAL SURVEY

5. LEASE N. 1. 067707

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

	-			· ·	
6	IF INT	HAN	1 1 2	ATTER OF TRIBE NAL	4 F

SUNDRY NOTICES AND R	REPORTS ON	WELLS
----------------------	------------	-------

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)

1.	cil well	\Box	gas weil		other			-
2.	MAM	E OF	OPERA"	TOR				_
	Parr	olei	im Exp	lora	ition	Company,	Inc.	Ι-

3. ADDRESS OF OPERATOR P.O. Box 809, Roswell, New Mexico 88201

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See spece 17 below.)
AT SURFACE: 1980' FNL & 660' FEL

AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL	TO:	SUBSEQUENT	REPORT	OF:
TEST WATER SHUT-OFF				
FRACTURE TREAT				
SHOOT OR ACIDIZE				
REPAIR WELL				
PULL OR ALTER CASING				
MULTIPLE COMPLETE				
CHANGE ZONES				

 \Box

10. FIELD OR WILDCAT NAME

11. SEC., T., R., M., OR BLK. AND SURVEY OR

<u> Siete - Federal</u>

AREA Section 17-8S-31E

12. COUNTY OR PARISH 13. STATE N.M.

14. API NO.

9. WELL NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD) 4210 GL

chengs on Form 9–330.)

Set @ ___

NOTE: Report results of multiple completion or zone

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-29-84 M.I.R.U.P.U. & Reverse Unit. Mixed 70 sxs of gel w/140 bbls water. R.I.H. w/ 3-7/8" bit & 2-3/8" tubing. Tagged bottom at 624'. Washed down to 726'. Worked for four hrs. - could not get past - S.D.O.N.

8-30-84 Washed back down to 726'. Circulated hole w/mud. Set 50 sxs. cement plug w/ 4% CACL for 726' to 566'. WOC 1 hr. Tagged top of cement at 566'. Set 40 sxs cement plug from 450' to 300'. Set 20 sxs cement plug from 60' to surface. R.D.M.O.P.U.

9-1-84 Installed dry hole marker.

ABANDON® (cther)

SIGNED _

Subsurface Safety Velva: Manu. and Type

18. I hereby cartify that the foregoing is true and correct

Ully Doglam TITLE Secretary/Treas. DATE 9-4-84

APPROVED (This space for Federal or State office use)

(Orig. Sad.) PETER W. CHISTER

CONDITIONS OF APPROVAL IF ANY:

MAY 8 1384

7 13 8411

2/1/86

*See Instructions on Reverse Side