Form 9-331 (May 1963)	DEP	ARTM	ENT OF		ERMO	(Other in		<u>.</u>	5. LEASE DESIG			
(Do not	SUNDRY use this form for Use "/	NOTIC	ES AND	REPOR	rs Ox	WELLS	BY t reservoir.		NM 3 6. IF INDIAN, A	1648 ALLOTTEE OR	TRIBE NA	ME
OIL WELL	GAS [THER		Hole		UL 13 1			7. UNIT AGREES	MENT NAME		
	y G. Bar	ton J	····			O. C. I			8. FARM OR LE Betty 9. WELL NO.		eral	
P. O. Box 978 Hobbs, New Mexico 88240 4. Location of well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FNL & 990 FWL									1 10. FIELD AND FOOL, OR WILDCAT S.E. Chaves Queen Gas 11. SEC.AT. E.G., ORSEDEND OIL SURVEY OR AREA			
14. PERMIT NO.			15. ELEVATION						Sec. 3,			R. 30 E
			3848 9	11., 3	858 - E	of.			Chaves		New M	Mexico —
16.		eck App		x To Indico	ate Natu	re of Noti	ce, Report,		ther Data ENT REPORT OF:			
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)*										any erti-		
	Permiss	35	Sx at	each o	of the	ese int	iven ll	;]	3-83 by 2060-216 1350-145 1100-120 670- 57	0 0 0	∍.	
		10	sx plu	ıg at s	urtac	e						
	Plug do Waiting						_		11-28-83			
							•		CES NOV 28	1083		
	,						,					
								Dil & GAS				
18. I hereby cer	try that the for		rue and corre	TITLE	Age	nt		<u>-</u>	DATE _		28, 1	L983
(C	for Federal or S Orig. Sgd.) PI BY IS OF APPROVE	ETER W	CHESTE	R TITLE					DATE _			
	1		Man A	*See Instru	ctions or	n Reverse S	ide					