	EPARTMEI OF THE INTER	RIOR (Other instruction re-	Expires August 3 5. LEASE DESIGNATION A	o. 1004-0 1, 1985
	BUREAU OF LAND MANAGEMEN	1T	NM-0347394	ND SERIAL
SUNDR	Y NOTICES AND REPORTS	ON WELLS	6. IF INDIAN, ALLOTTEE	OR TRIBE N
(Do not use this form	n for proposals to drill or to deepen or plug e "APPLICATION FOR PERMIT—" for such I	back to a different reservoir.		ILIBE N
017	Tot such	proposais.)		
WELL KX WELL	OTHER	_	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR			9 -	
Yates Energy Cor	poration		8. FARM OR LEASE NAME	
	D		South Tomahawk	Federa
4. LOCATION OF WELL (Repor	Roswell, NM 88202-2323 t location clearly and in accordance with any		# 1	
	and in accordance with any	State requirements.	10. FIELD AND POOL, OR W	ILDCAT
E			Tomahawk San A	
1980' FNL &	330' FWL	Ī	11. SEC., T., R., M., OR BLK. SURVEY OR AREA	AND
14 panus				
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	, RT, GR, etc.)	Section 6-T8S-32	2E
	4433.3 GL		12. COUNTY OR PARISH 13	3. STATE
16.	heck Appropriate Roy To Indiana	1	Chaves	MM
NOTICE	heck Appropriate Box To Indicate N	ature of Notice, Report, or Ot	her Data	
TEST WATER SHUT-OFF			NT REPORT OF:	
PRACTURE TREAT	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
SHOOT OR ACIDIZE	MULTIPLE COMPLETE ABANDON®	FRACTURE TREATMENT	ALTERING CABING	
REPAIR WELL	CHANGE PLANS	SHOOTING OR ACIDIZING	ABANDONMENT*	-
(Other)	LETES OPERATIONS (Clearly state all pertinent is directionally drilled, give subsurface location	(Other)(NOTE: Report results of	multiple completion on V	_ -
<ol> <li>Set a CIBP @</li> <li>Dump 35' cem</li> </ol>	ent on CIBP.			
J. Cut csg. @ a	pprox. 1700'			
4. Place a 25 s	x. cement plug 50' inside s	Stub and another 50!		
A		and another 50 of	IL OI CSO, stub	
D. Place a 25 a			00g. Stub	and
D. Place a 25 a				and
6. Place a 25 s $6.$ Place 10 sx.	x. plug 300 - 400' - Tag pl		og. Stub	and
6. Place a 25 s $6.$ Place 10 sx.	x. plug 300 - 400' - Tag pl plug @ surface. Minimum e and dry hole number.		ANO.	and
6. Place a 25 s $6.$ Place 10 sx.	x. plug 300 - 400' - Tag pl		ELAND MA	and
6. Place a 25 s $6.$ Place 10 sx.	x. plug 300 - 400' - Tag pl		OF LAND MANA	and
6. Place a 25 s $6.$ Place 10 sx.	x. plug 300 - 400' - Tag pl		ELAND MA	and
6. Place a 25 s $6.$ Place 10 sx.	x. plug 300 - 400' - Tag pl		OF LAND MANAGED RESOURCES	and
6. Place a 25 s $6.$ Place 10 sx.	x. plug 300 - 400' - Tag pl		ELAND MA	and
6. Place a 25 s $6.$ Place 10 sx.	x. plug 300 - 400' - Tag pl		OF LAND MANAGED RESOURCES	and
6. Place a 25 s $6.$ Place 10 sx.	x. plug 300 - 400' - Tag pl		OF LAND MANAGED RESOURCES	and
5. Place a 25 s 6. Place 10 sx. 7. Install plat	x. plug 300 - 400' - Tag pl plug @ surface. Minimum e and dry hole number.		JUL 09 1991	and
6. Place a 25 s 6. Place 10 sx. 7. Install plat  8. I hereby certify that the fore	x. plug 300 - 400' - Tag pl plug @ surface. Minimum e and dry hole number.		OF LAND MANAGED RESOURCES	and
5. Place a 25 s 6. Place 10 sx. 7. Install plat	plug @ surface. Minimum e and dry hole number.		JUL 09 1991	and
6. Place a 25 s 6. Place 10 sx. 7. Install plat	rolar in true and correct  TITLE Ag	ng. 50'plug	JUL 09 1991	and
8. I hereby certify that the fore SIGNED  (This space for Federal or St.)	rolog by true and correct  TITLE Agate office use)	ng. 50'plug	JUL 09 1991	and
8. I hereby certify that the fore	rolog by true and correct  TITLE Agate office use)	ng. 50'plug	JUL 09 1991	and
8. I hereby certify that the fore SIGNED  (This space for Federal or St.)	rolog by true and correct  TITLE Agate office use)	ng. 50'plug	JUL 09 1991  DATE 6/28/91	and
I hereby certify that the fore  SIGNED  (This space for Federal or St.)  APPROVED BY	rolog by true and correct  TITLE Agate office use)	gent	JUL 09 1991  DATE 6/28/91	and

RECEIVED

JUL 1 9 1991

OCE HOSSS CAPICE