

|                       |  |
|-----------------------|--|
| NO. OF COPIES DESIRED |  |
| DISTRIBUTION          |  |
| SANTA FE              |  |
| FILE                  |  |
| U.S.G.A.              |  |
| LAND OFFICE           |  |
| OPERATOR              |  |

CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO KEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

|                                                                                                       |
|-------------------------------------------------------------------------------------------------------|
| 10. Indicate Type of Lease<br>State <input checked="" type="checkbox"/> Perm <input type="checkbox"/> |
| 11. State Oil & Gas Lease No.<br>LG-1397                                                              |
| 7. Unit Agreement Name                                                                                |
| 8. Perm or Lease Name<br>Chaveroo State                                                               |
| 9. Well No.<br>2                                                                                      |
| 16. Field and Pool, or Unit<br>Chaveroo - San Andres                                                  |
| 12. County<br>Chaves                                                                                  |

|                                                                                                                                                                                               |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. Name of Operator<br>Siete Oil and Gas Corporation                                                                                                                                          |
| 2. Address of Operator<br>P.O. Box 2523, Roswell, New Mexico 88201                                                                                                                            |
| 3. Location of Well<br>WELL LETTER <u>F</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>2028</u> FEET FROM<br>THE <u>West</u> LINE, SECTION <u>4</u> TOWNSHIP <u>8N</u> RANGE <u>32E</u> MAP. |

|                                               |
|-----------------------------------------------|
| 15. Elevation (Show whether DF, RT, CA, etc.) |
|-----------------------------------------------|

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

|                                                |                                                 |
|------------------------------------------------|-------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/>       |
| TEMPERARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>           |
| FULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input checked="" type="checkbox"/> P & A |

SUBSEQUENT REPORT OF:

|                                                      |                                               |
|------------------------------------------------------|-----------------------------------------------|
| REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| COMMENCE DRILLING OPER. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 100.

- (1) 122' Plug 4272' to 4150' tagged (50 sxs Class "C" cement)
- (2) Cut 4½" casing off at 3300'
- (3) 180' Plug 3350 to 3170' tagged (60 sxs Class "C" cement)
- (4) 111' Plug 1821 to 1710' tagged (50 sxs Class "C" cement)  
Bottom of 8 5/8" surface at 1777'.
- (5) 10' Plug set in top of 8 5/8" surface with marker

7/A 12/84

I hereby certify that the information above is true and correct to the best of my knowledge and belief.

Signed [Signature] TITLE President DATE 2-28-85  
Oil & Gas Inspector ADD 1 = 1986

RECEIVED

MAR -7 1985

2-2-85  
FBI - NEW YORK

# WELL DATA

COMPANY

Siete O.G. Corp

LOCATION

CHAUVERON #2

## PLUG & ABANDON

12-6-84 -

08:47 Rig Up Unit

09:30 Pull Rods

12:30 Circulate Hole & Set 1st Plug @ 4272' TAGGED @ 4150

2:30 Bell Survey Free Point @ 3300'

4:30 Run Csg. Cutter - Unable To Get Past 1371' (HARDENED)

6:00 SHUT DOWN

12-7-84

07:30 Run In Hole w/ TBG To 2200' To Hot Water Pannell

Monument H. Oilier On Loc @ 10:00 (2 1/2 Hrs Late)

12:30 Well Hot Watered Pull TBG & Go In Hole w/ Cutter, Unable To

Get Past 2200' Pull Cutter & Run Gauge Ring To 3355'

Run Cutter & To 3300' & Cut Csg.

3:00 PM

Start Pulling Csg.

5:00 PM SHUT DOWN

12-8-84

07:30 Complete Casing Pulling


10:15 Go In Hole w/ TBG To 3350'

11:15 SET 2ND Plug Plug Tagged @ 3170'

SET 3RD Plug @ 1827' TAGGED @ 1710'

SET 4TH Plug IN TOP OF 8 5/8" @ SURFACE

5:00 Job Complete SHUT DOWN



RECEIVED

MAR - 4 1985

C.C.D.  
HUMAN RIGHTS OFFICE